

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9909220125 DOC.DATE: 99/08/23 NOTARIZED: NO DOCKET #
 FAGIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316
 AUTH.NAME AUTHOR AFFILIATION
 BAKKEN, A.C. Indiana Michigan Power Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards revised page 2 to "1998 Annual Environ Operating Rept," for DC Cook Nuclear Plant, correcting omission to App I.

DISTRIBUTION CODE: IE25D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 3 + 1
 TITLE: Environmental Monitoring Rept (per Tech Specs)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	BARNHILL, E	1 1	STANG, J	1 1
INTERNAL:	<u>FILE CENTER 01</u> RGN3 FILE	1 1 1 1	NRR/DIPM/EPHP	1 1
EXTERNAL:	NRC PDR	1 1		

MICROFILMED

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 6 ENCL 8

Er-

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5901



August 23, 1999

C0899-05

Docket Nos.: 50-315
50-316

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Stop O-P1-17
Washington, D.C. 20555-0001

Donald C. Cook Nuclear Plant Units 1 and 2
CORRECTION TO 1998 ANNUAL ENVIRONMENTAL OPERATING REPORT

Reference: Letter from A. C. Bakken III to NRC dated April 30, 1999, "Donald C. Cook Nuclear Plant Units 1 and 2, ANNUAL ENVIRONMENTAL OPERATING REPORT, JANUARY 1, 1998, TO DECEMBER 31, 1998", (AEP:NRC:0806S)

The purpose of this letter is to correct an omission to Appendix I, Non-Routine Reports section of the 1998 Annual Environmental Operating Report, which was transmitted with the referenced letter.

During a routine audit of the Environmental Protection Plan, it was identified that a spill from the heating boiler on August 1, 1998 had not been reported in the 1998 Annual Environmental Operating Report. A revised page is enclosed with the correction marked in the margin. Please replace page 2 of Appendix I with the corrected page.

This condition has been entered into the corrective action program.

Should you have any questions, please contact Mr. Gordon Arent, Assistant Director of Regulatory Affairs, at (616) 465-5901, extension 1575.

Sincerely,

A. C. Bakken III
Site Vice President

/dms

Enclosure

220021

9909220125 990823
PDR ADDCK 05000315
R PDR

c: J. E. Dyer
MDEQ - DW & RPD
NRC Resident Inspector, w/enclosure
R. P. Powers
R. Whale MPSC
1998 Annual Environmental Operating Report
Retention Number 4.5

bc: D. M. Fitzgerald/J. P. Carlson
FOLIO, w/enclosure
R. C. Godley/G. P. Arent/J. Burford
M. W. Rencheck/D. J. Garner/S. A. Greenlee
J. F. Stang, Jr., NRC - Washington, DC - w/enclosure