

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	1	1	0	1	7	9	8	1	1	3	0	7	9	9
60	61								68	69						74	75							80
DOCKET NUMBER										EVENT DATE										REPORT DATE				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

08 | _____ 8

SYSTEM CODE S E (11)		CAUSE CODE E (12)		CAUSE SUBCODE A (13)		COMP. SUBCODE Z (15)		VALVE SUBCODE Z (16)	
EVENT YEAR 7 9 (17)		SEQUENTIAL REPORT NO. 0 4 1 (24)		OCCURRENCE CODE 0 3 (28)		REPORT TYPE L (30)		REVISION NO. 0 (32)	
ACTION TAKEN X (18)		FUTURE ACTION D (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 (22)	
ATTACHMENT SUBMITTED N (23)		NPRD-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER N (25)		COMPONENT MANUFACTURER W 2 0 0 (26)			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	CAUSE OF THE FAILURE IS PRESENTLY UNKNOWN. TROUBLESHOOTING IS IN PROGRESS
1	1	WITH REPAIRS TO FOLLOW. A FOLLOW-UP REPORT WILL BE SUBMITTED.
1	2	
1	3	
1	4	

7 8 9
FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)
1 5 H 0 0 0 NA B SURVEILLANCE TEST

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 10 34 NA

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

1		9		Z		42		NA		43		7912070377	
7	8	9	10										

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 00
 PUBLICITY (45) NRC USE ONLY
 ISSUED (44) NA
 2 0
 616 465 5001 EXT 300

PHONE: 616-465-5901, EXT.398

