

## LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 2 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 57 CAT 58

7 8 9 14 15 25 26 30 57 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

REPORT SOURCE	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80				
	L	6	0	5	0	0	0	3	1	6	7	1	1	0	2	7	9	8	1	2	0	3	7	9	9
	DOCKET NUMBER									EVENT DATE					REPORT DATE										

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | DURING SURVEILLANCE INSPECTION PER T.S. 4.6.5.9, THE ICE CONDENSER DIVIDER  
0 3 | BARRIER SEAL WAS FOUND TO HAVE CRACKS IN THE RUBBER. IN SOME AREAS,  
0 4 | THE CRACKS DID PENETRATE THE SEAL. HOWEVER THE MAJOR PORTION OF THE  
0 5 | SEAL INTEGRITY REMAINED INTACT. THE EVENT DID NOT JEOPARDIZE PUBLIC  
0 6 | HEALTH AND SAFETY. A SIMILAR EVENT WAS REPORTED AS RO 79-029/03L-0,  
0 7 | DOCKET NO. 050315.

[illegible]

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE CAUSE AND CORRECTIVE ACTION ARE UNDER STUDY AND A SUPPLEMENTAL

1 1 REPORT WILL BE SUBMITTED PRIOR TO ENTERING MODE 4.

1 2

1 3

1 4

8 9  
FACILITY STATUS (1) (5) (H) (28) % POWER (0) (0) (0) (29) OTHER STATUS (30) NA  
7 8 9 10 11 12 13 14  
ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA  
7 8 9 10 11 12 13 14  
PERSONNEL EXPOSURES  
NUMBER TYPE DESCRIPTION (39) NA  
7 8 9 10 11 12 13 14  
PERSONNEL INJURIES  
NUMBER DESCRIPTION (41) NA  
7 8 9 10 11 12 13 14  
LOSS OF OR DAMAGE TO FACILITY  
TYPE DESCRIPTION (43) NA  
7 8 9 10 11 12 13 14  
PUBLICITY  
ISSUED DESCRIPTION (45) NA  
7 8 9 10 11 12 13 14  
7912100291  
NRC USE ONLY  
78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER DAVID G. WIZNER

PHONE: 465-5901, EXT.398

