

**LICENSEE EVENT REPORT**

**CONTROL BLOCK:**

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	(2)	0	0	0	0	0	0	0	0	0	0	0	(3)	4	1	1	1	1	(4)			(5)	
8	9	LICENSEE CODE					14	15	LICENSE NUMBER											25	26	LICENSE TYPE					30	57	CAT	58

**CON'T**

0	1	REPORT SOURCE																		DOCKET NUMBER																		EVENT DATE																		REPORT DATE																	
8		60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																																																			
		L	6	0	5	0	0	0	3	1	6	7	0	2	2	3	8	0	8	0	3	2	1	8	0	9																																															

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | WHILE PERFORMING THE WEEKLY TURBINE STOP AND CONTROL VALVE TESTING A

03 | REDUCTION IN THE REACTOR COOLANT SYSTEM PRESSURE OCCURRED. THE PRESSURE

04 | DROPPED TO 2215 PSIA WHICH IS 5 PSI BELOW THE MINIMUM PRESSURE LIMIT

05 | SPECIFIED IN TECHNICAL SPECIFICATION 3.2.5.b. THE PRESSURE RECOVERED

06 | RAPIDLY AND THERE WAS NO THREAT TO THE PUBLIC HEALTH AND SAFETY.

0	7
---	---

0	8	
---	---	--

0 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

Z Z (11) E (12) A (13) C K T B R K (14) A (15) Z (16)

(17) LER/RO REPORT NUMBER 80 —
 EVENT YEAR 011
 SEQUENTIAL REPORT NO. /
 OCCURRENCE CODE 03
 REPORT TYPE L —
 REVISION NO. 0

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER				
Z	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	N	24	L	25	C	7	7	C	26
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 INVESTIGATION FOUND THAT 6 OF 78 PRESSURIZER HEATERS WERE INOPERABLE DUE TO

1 1 | TRIPPED SUPPLY BREAKERS. THE BREAKERS WERE RESET AND THE HEATERS HAVE BEEN

1 2 | FUNCTIONING NORMALLY SINCE. THIS CONDITION HAS BEEN REVIEWED WITH ALL.

1 3 LICENSED OPERATORS, IN CASE A SIMILAR SITUATION SHOULD OCCUR.

1	4
---	---

8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) 1 5 E 1 0 0 (29) NA OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 Z 33 Z 34 NA

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	

8	9	11	12	13	80
PERSONNEL INJURIES					
NUMBER	DESCRIPTION (41)				

1	8	0	0	0	40	NA	80
8	9	11	12	LOSS OF OR DAMAGE TO FACILITY (43)			
TYPE - DESCRIPTION							

TYPE		DESCRIPTION
1	9	Z (42) NA

8 9 10 80  
 PUBLICITY  
 ISSUED DESCRIPTION (45)  
 2 0 N (44) NA  
 NRC USE ONLY

8 9 10 68 69 80

NAME OF PREPARER C. E. MURPHY

800.4010 451

PHONE: 465-5901 X-316

**NRC USE ONLY**