

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION-NBR:8010080515 DOC.DATE: 80/10/01 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
AUTH.NAME AUTHOR AFFILIATION
BROWN,M.S. Indiana & Michigan Electric Co.
RECIP.NAME RECIPIENT AFFILIATION
Region 3, Chicago, Office of the Director

SUBJECT: LER 80-022/03L-0: on 800906, during normal operation, low flow
alarm received on radiation monitors R-11 & 12 indicating
inoperable monitor. Caused by L-100 shaft coupling failure.
Coupling replaced, air monitor tested & returned to svc.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
TITLE: Incident Reports

NOTES: I&E: 3 copies all material.

05000315

ACTION:	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME:	COPIES	
			LTTR	ENCL		LTTR	ENCL
ACTION:	VARGA, S.	04	3	3			
INTERNAL:	A/D COMP&STRU06		1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08		1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10		1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12		1	1	A/D TECHNOLOG13	1	1
	ACC EVAL BR 14		1	1	AEOD	2	2
	ASLBP/J. HARD		1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16		1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18		1	1	D/DIR, HUM FAC19	1	1
	DIR, ENGINEER120		1	1	DIR, HUM FACI S21	1	1
	DIR, SYS INTEG22		1	1	EFF TR SYS BR23	1	1
	EQUIP QUALI BR25		1	1	GEOSCIENCES 26	1	1
	I&C SYS BR 29		1	1	I&E 05	2	2
	JORDAN, E./IE.		1	1	LIC GUID BR 30	1	1
	LIC QUAL BR 31		1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33		1	1	MPA	3	3
	NRC PDR 02		1	1	OP EX EVAL BR34	3	3
	OR ASSESS BR 35		1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39		1	1	REACT SYS BR 40	1	1
	REG FILE 01		1	1	REL & RISK A 41	1	1
	SFTY PROG EVA42		1	1	STRUCT ENG BR44	1	1
	SYS INTERAC B45		1	1			
EXTERNAL:	ACRS	46	16	16	LPDR 03	1	1
	NSIC	05	1	1	TERA: DOUG MAY	1	1

OCT 9 1980

TOTAL NUMBER OF COPIES REQUIRED: LTTR 72 ENCL 72

A0
4

60
1

