



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

December 22, 1980

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

On December 15, 1980 we verbally informed the NRC Region III Resident Inspector, Mr. E. Swanson, and NRC RO:III by letter of our violation of Unit 2 Technical Specifications by having two spray header isolation valves shut. The attached Licensee Event Report 80-033/01-T-0 provides the results of the investigation and corrective action taken.

Sincerely,

D. V. Shaller
Plant Manager

/pk

cc: J. E. Dolan
R. S. Hunter
R. W. Jurgensen
R. F. Kroeger
R. W. Kilburn
E. Swanson/N. DuBry NRC RO:III
R. C. Callen MPSC
G. Charnoff, Esq.
J. M. Hennigan
W. Lavallee EPRI
PNSRC
J. F. Stietzel
E. L. Townley
Dir., MIPC (4 copies)
Dir., IE (40 copies)

5 NRC
SERVICES
FCA

2 PM 5 21

REGISTERED
UNIT

A002
s
11

8101050

472

DEC 29 1980

15

15. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.