

## ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8907140169 DOC. DATE: 89/07/05 NOTARIZED: NO DOCKET #  
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTH. NAME AUTHOR AFFILIATION  
 SMITH, W.G. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 890531, Fire Door 392, auxiliary bldg access  
 control entry door, declared inoperable.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

## NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA	1 1	PD3-1 PD	1 1
	STANG, J	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	IRM/DCTS/DAB	1 1
	NRR/DEST/ADE 8H	1 1	NRR/DEST/ADS 7E	1 0
	NRR/DEST/CEB 8H	1 1	NRR/DEST/ESB 8D	1 1
	NRR/DEST/ICSB 7	1 1	NRR/DEST/MEB 9H	1 1
	NRR/DEST/MTB 9H	1 1	NRR/DEST/PSB 8D	1 1
	NRR/DEST/RSB 8E	1 1	NRR/DEST/SGB 8D	1 1
	NRR/DLPQ/HFB 10	1 1	NRR/DLPQ/PEB 10	1 1
	NRR/DOEA/EAB 11	1 1	NRR/DREP/RPB 10	2 2
	NUDOCS-ABSTRACT	1 1	REG FILE 02	1 1
	RES/DSIR/EIB	1 1	RES/DSR/PRAB	1 1
	RGN3 FILE 01	1 1		
EXTERNAL:	EG&G WILLIAMS, S.	4 4	FORD BLDG HOY, A	1 1
	L ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC MAYS, G	1 1
	NSIC MURPHY, G.A	1 1		

## NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL 42

R  
I  
D  
S  
/  
A  
D  
S  
/  
A  
D  
D  
S

*Handwritten signature/initials*

Indiana Michigan  
Power Company  
Cook Nuclear Plant  
One Cook Place  
Bridgman, MI 49106  
616 465 5901



July 5, 1989

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2  
Docket Nos. 50-315 and 50-316  
License Nos. DPR-58 and DPR-74

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Attn: A.B. Davis

Dear Mr. Davis:

This Special Report is being submitted in accordance with Technical Specification 3.7.10 action to inform you that the following two fire barriers have been inoperable longer than the seven days allowed by Technical Specification 3.7.10.

Fire Door 392, the Auxiliary Building access control entry door, was declared inoperable on May 31, 1989, due to the failure of the door knob mechanism. After further inspection it was determined that the entire door should be replaced. A new door was ordered and is anticipated to be obtained, installed, and declared operable by September 15, 1989. A fire watch, as required by Technical Specification 3.7.10 Action A, is being maintained while the door is inoperable.

The TSI fire retardant material was removed from the fire panel separating the unit One East Component Cooling Water Pump from the Spare Component Cooling Water Pump on June 14, 1989. At that time a fire watch, as required by Technical Specification 3.7.10 Action A, was established and remained in effect until the TSI fire retardant material was returned to operable status on June 23, 1989.

Respectfully

*W.G. Smith Jr.*  
W.G. Smith Jr.  
Plant Manager

c: See Attached Distribution List

8907140169 890705  
PDR ADOCK 05000315  
S PDC

*FE22*  
*1/0*



c: D.H. Williams, Jr.  
A.B. Davis, Region III  
M.P. Alexich  
P.A. Barrett  
J.E. Borggren  
R.F. Kroeger  
NRC Resident Inspector  
J.F. Stang  
R.C. Callen  
G. Charnoff, Esq.  
Dottie Sherman, ANI Library  
D. Hahn  
INPO  
PNSRC  
A.A. Blind  
S.J. Brewer/B.P. Lauzau