

# LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

1

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES** (10)

0 2 AFTER THE INSTALLATION OF AN ADDITIONAL MOTOR DRIVEN AUX FEEDWATER  
0 3 PUMP (MDAFP) SUBSEQUENT TESTING OF THE WEST - MDAFP DURING BLACKOUT  
0 4 CONDITIONS REVEALED THAT TWO SAFETY INJECTION RELAY TIMERS EXCEEDED  
0 5 THE TOLERANCE ALLOWED BY T.S. 4.8.1.1.2.C.2. THE AFFECTED PUMPS WERE  
0 6 THE 2W-RHR PUMP AND THE 2 W-CCW PUMP.  
0 7  
0 8

09		SYSTEM CODE E G		11	CAUSE CODE E		12	CAUSE SUBCODE A		13	COMPONENT CODE R E L A Y S					14	COMP. SUBCODE M		15	VALVE SUBCODE Z		16				
7	8	9	10		11		12				13				14		15			16						
17		LER/RO REPORT NUMBER		EVENT YEAR 8 0		21	22	SEQUENTIAL REPORT NO. 0 2 8		24	25	26	OCCURRENCE CODE 0 3		28	29	REPORT TYPE L		30	31	REVISION NO. 0		32			
ACTION TAKEN E		18	FUTURE ACTION Z		19	EFFECT ON PLANT Z		20	SHUTDOWN METHOD Z		21	HOURS 0 0 0 0		22	ATTACHMENT SUBMITTED N		23	NPRD-4 FORM SUB. Y		24	PRIME COMP. SUPPLIER N		25	COMPONENT MANUFACTURER A 1 0 9		26
33		34			35				36				37			40		41		42		43		44		47

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE 2W-RHR PUMP START TIME EXCEEDED THE T.S. ALLOWABLE VALUE BY 4 PER-

1 1 CENT WHILE THE 2W-CCW PUMP EXCEEDED THE T.S. ALLOWANCE BY 1.3 PERCENT.

1 2 THE TIMER RELAYS ARE MANUFACTURED BY AGASTAT, MODEL NO. 7012. THE

1 3 TIMERS WERE READJUSTED TO WITHIN ALLOWABLE VALUES. THIS EVENT WAS

1 4 ATTRIBUTED TO INSTRUMENT DRIFT, AND NO FURTHER ACTION IS PLANNED.

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
1	5	H	28	0	0	0	29	NA	B	31	DESIGN CHANGE TEST	32
ACTIVITY RELEASED		CONTENT OF RELEASE			AMOUNT OF ACTIVITY		LOCATION OF RELEASE					
1	6	Z	33	Z	34	NA	35	NA	36			
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION						
1	7	0	0	0	37	Z	38	NA	39			
PERSONNEL INJURIES		NUMBER		DESCRIPTION								
1	8	0	0	0	40	NA	41					
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION								
1	9	Z	42	NA	43							
PUBLICITY ISSUED		DESCRIPTION										
2	0	NA	44	NA	45							
8008040094										NRC USE ONLY		

NAME OF PREPARER J. L. Rischling

PHONE: 616-465-5901