

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	0	9	0	2	8	0	8	1	0	0	3	8	0	9
60	61								68	69						74	75							80
DOCKET NUMBER										EVENT DATE										REPORT DATE				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE I B 9 8		CAUSE CODE E 11		CAUSE SUBCODE G 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE S 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 17		EVENT YEAR 8 0 21 22		SEQUENTIAL REPORT NO. 0 3 1 24 25 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN E 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 22 37 40		ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. Y 24	
PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER F 1 8 0 26 44 47											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9
FACILITY STATUS (28) 1 5 E
% POWER 1 1 0 0 (29) NA
OTHER STATUS (30)
METHOD OF DISCOVERY (31) B
DISCOVERY DESCRIPTION (32) SURVEILLANCE TESTING

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA	(39)			

8		9		10		11		12	
TYPE		DESCRIPTION		LOSS OF OR DAMAGE TO FACILITY		(43)			
1	9	Z	(42)	NA				8010090362	

		PUBLICATION			NRC USE ONLY									
ISSUED		DESCRIPTION		(45)										
2	0	N	(44)	NA										

NAME OF PREPARER S. D. DELONG

PHONE: 616-465-5901