

## LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	-	0	0	0	0	0	-	0	0	3					4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT		58

**REPORT  
SOURCE**

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING AN ICE CONDENSER INSPECTION, 21 INTERMEDIATE DECK DOORS WERE FOUND  
0 3 FROZEN AND DECLARED INOPERABLE PER T.S. 3.6.5.3. ACTION REQUIREMENTS WERE  
0 4 MET. THE OTHER 171 DOORS REMAINED OPERABLE. THIS EVENT HAD NO PUBLIC  
0 5 HEALTH AND SAFETY CONSEQUENCES. PREVIOUS EVENTS INCLUDE:" RO 79-036/03L-0;  
0 6 79-045/036-0; 79-060/03L-0; AND 80-021/03L-0.  
0 7  
0 8

SYSTEM CODE S B 11		CAUSE CODE B 12		CAUSE SUBCODE A 13		COMP. SUBCODE D 15		VALVE SUBCODE Z 16	
SEQUENCE REPORT NO. 0 2 4		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0			
ACTION TAKEN X 18		FUTURE ACTION F 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22	
ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER W 1 2 0 26			

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE ICE WAS CHIPPED FREE AND REMOVED, RETURNING THE FROZEN DOORS TO AN  
1 1 OPERABLE CONDITION. MOISTURE CONDENSING ON THE TOP DECK DOOR DIVIDER  
1 2 BEAMS WAS FOUND TO BE THE WATER/ICE SOURCE. DESIGN CHANGE PER RFC DC 12-  
1 3 1791 WAS INITIATED TO INSULATE THE BEAMS TO PREVENT CONDENSATION. ICE CONDENSER  
1 4 INSPECTION HAS BEEN INCREASED FROM THREE TIMES WEEKLY TO DAILY.

7 8 9  
FACILITY STATUS  
1 5 E 28  
% POWER  
1 0 0 29  
OTHER STATUS 30 N/A  
METHOD OF DISCOVERY  
A 31  
DISCOVERY DESCRIPTION 32 NON-ROUTINE INSPECTION  
80

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  
1 6 Z (33) Z (34) N/A

LOCATION OF RELEASE (36)  
N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) N/A (39)				

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
		N/A	

7		8		9		11		12	
1		2		3		4		5	
TYPE		DESCRIPTION		LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION	
1	9	Z	(42)	N/A		(43)		8010210671	

7		8	9	10														80												
		PUBICITY			NRC USE ONLY																									
ISSUED		DESCRIPTION																												
2 0		N (44)			N/A																									
7		8	9	10														68	69											80

NAME OF PREPARER R. H. PIEHL

NRC USE ONLY  
 68 69 80  
 PHONE: 616-465-5901, EXT. 1036

2011