

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⁽¹⁰⁾

SYSTEM CODE 9 10		CAUSE CODE 11 12		CAUSE SUBCODE 12 13		COMPONENT CODE 13 14		COMP. SUBCODE 14 15		VALVE SUBCODE 15 16	
I E		E		E		E L E C O N		Z		Z	
7 8		9 10		11 12		13 14		15 16		17 18	
LER/RO REPORT NUMBER 17		EVENT YEAR 21 22		SEQUENTIAL REPORT NO. 24 26		OCCURRENCE CODE 28 29		REPORT TYPE 30 31		REVISION NO. 32	
8 9		8 0		0 3 5		0 3		L		0	
10 11		12 13		14 15		16 17		18 19		20 21	
ACTION TAKEN 33 34		FUTURE ACTION 35 36		EFFECT ON PLANT 37 38		SHUTDOWN METHOD 39 40		HOURS 41 42		ATTACHMENT SUBMITTED 43 44	
A		Z		C		B		0 0 7		N	
18 19		20 21		22 23		24 25		26 27		28 29	
30 31		32 33		34 35		36 37		38 39		40 41	
NPRD-4 FORM SUB. 42		PRIME COMP. SUPPLIER 43		COMPONENT MANUFACTURER 44 45 46 47		48 49		50 51		52 53	
Y		Z		X 9 9 9		54 55		56 57		58 59	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7 8 9
FACILITY STATUS
1 5 C (28)
% POWER
0 0 0 (29)
OTHER STATUS. (30) NA
METHOD OF DISCOVERY
B (31)
DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION
80

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	(37)	Z	(38)	NA	(39)	

7		8	9	11		12	
TYPE		LOSS OF OR DAMAGE TO FACILITY					
		DESCRIPTION					
1	9	Z	(42)	NA			(43) 8101080397

7		8	9	10		80											
				PUBLCITY		NRC USE ONLY											
		ISSUED		DESCRIPTION													
2 0		N		(44) NA													
7		8	9	10		68 69 80											

NAME OF PREPARER Jack L. Rischling

PHONE: (616) 465-5901