

DOCKET NO.
UNIT NAME
DATE
COMPLETED BY
TELEPHONE
PAGE

50 - 316
D.C. Cook Unit 2
January 6, 1998
JF Center
616-697-5098
1 of 1

MONTHLY OPERATING ACTIVITIES - November 1997

HIGHLIGHTS

The unit entered this reporting period in Mode 6 at 0% RTP.

The unit exited this reporting period in Mode 5 at 0% RTP..

There were no challenges to the pressurizer safety valves or power operated relief valves.

Gross electrical generation for the month of December was 0 MWh.

DETAILS*

10/13/97	0500	U2R97 Cycle 11 - 12 refueling outage begins.
12/05/97	0938	Entered Mode 5.

9801140267 971231 980108
PDR ADOCK 05000316
R PDR

* All time entries are Eastern Standard Time (EST).

DOCKET NO.	50 - 316
UNIT NAME	D.C. Cook Unit 2
DATE	January 6, 1998
COMPLETED BY	JF Center
TELEPHONE	616-697-5098
PAGE	1 of 1

UNIT SHUTDOWNS AND POWER REDUCTIONS - NOVEMBER 1997

NO.	DATE	TYPE ¹	DURATION HOURS	REASON ²	METHOD OF SHUTTING DOWN REACTOR ³	LICENSEE EVENT REPORT NO.	SYSTEM CODE ⁴	COMPONENT CODE ⁵	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
334	101297	S	744.0	C	4	N/A	N/A	N/A	The scheduled refueling outage commenced while the unit had been shutdown to resolve design basis questions discovered during the NRC Architect and Engineering (AE) Inspection.

1 TYPE:
F: Forced
S: Scheduled

2 REASON:
A: Equipment Failure (Explain)
B: Maintenance or Test
C: Refueling
D: Regulatory Restriction
E: Operator Training and
License Examination
F: Administrative
G: Operational Error (Explain)
H: Other (Explain)

3 METHOD:
1: Manual
2: Manual Scram
3: Automatic Scram
4: Other (Explain)

4 SYSTEM:
Exhibit G - Instructions
for preparation of data
entry sheets for Licensee
Event Report (LER) File
(NUREG 0161)

5 COMPONENT:
Exhibit I: Same Source