

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9805220066      DOC. DATE: 98/05/15      NOTARIZED: NO      DOCKET #  
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315  
 AUTH. NAME      AUTHOR AFFILIATION  
 SAMPSON, J. R.      Indiana Michigan Power Co.  
 RECIP. NAME      RECIPIENT AFFILIATION  
                          Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 98-004-02, providing results of analyses performed by W. LER reduced from seven pages to six due to transferring details of root cause section to "Caused of Event," section.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 1+6  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

**NOTES:**

	RECIPIENT ID CODE/NAME	COPIES	L	T	R	ENCL	RECIPIENT ID CODE/NAME	COPIES	L	T	R	ENCL
	PD3-3 PD	1		1			STANG, J	1		1		
INTERNAL:	AEOD/SPD/RAB	2		2			AEOD/SPD/RRAB	1		1		
	<u>FILE CENTER</u>	1		1			NRR/DE/ECGB	1		1		
	NRR/DE/EELB	1		1			NRR/DE/EMEB	1		1		
	NRR/DRCH/HHFB	1		1			NRR/DRCH/HICB	1		1		
	NRR/DRCH/HOLB	1		1			NRR/DRCH/HQMB	1		1		
	NRR/DRPM/PECB	1		1			NRR/DSSA/SPLB	1		1		
	NRR/DSSA/SRXB	1		1			RES/DET/EIB	1		1		
	RGN3 FILE 01	1		1								
EXTERNAL:	L ST LOBBY WARD	1		1			LITCO BRYCE, J H	1		1		
	NOAC POORE, W.	1		1			NOAC QUEENER, DS	1		1		
	NRC PDR	1		1			NUDOCS FULL TXT	1		1		

**NOTE TO ALL "RIDS" RECIPIENTS:**

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTR      24      ENCL      24

C  
A  
T  
E  
G  
O  
R  
Y  
  
1  
  
D  
O  
C  
U  
M  
E  
N  
T

Indiana Michigan  
Power Company  
Cock Nuclear Plant  
One Cock Place  
Bridgman, MI 49106



May 15, 1998

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Operating Licenses DPR-58  
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

98-004-02

In addition to providing the results of analyses performed by Westinghouse, information previously provided was reorganized to transfer details of the root cause from the "Analysis of the Event" section to its proper location under "Cause of Event". This has resulted in the LER being reduced from 7 pages to 6.

Sincerely,

J. R. Sampson  
Site Vice President

/mbd

Attachment

c: A. B. Beach, Region III  
J. R. Sampson  
P. A. Barrett  
S. J. Brewer  
R. Whale  
D. Hahn  
Records Center, INPO  
NRC Resident Inspector

1/1  
IER2

9805220066 980515  
PDR ADDCK 05000315  
S PDR

