

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9812150143 DOC.DATE: 98/12/11 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
AUTH.NAME AUTHOR AFFILIATION
SAMPSON, J.R. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
RECIP.NAME RECIPIENT AFFILIATION
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-031-01, re potential common mode failure of RHR pumps due to use of inaccurate values. Commitment made by util, listed.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE:
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
PD3-3 PD	1	1	STANG, J	1	1
INTERNAL: AEOD/SPD/RAB	2	2	AEOD/SPD/RRAB	1	1
<u>FILE CENTER</u>	1	1	NRR/DE/ECGB	1	1
NRR/DE/EELB	1	1	NRR/DE/EMEB	1	1
NRR/DRCH/HICB	1	1	NRR/DRCH/HOHB	1	1
NRR/DRCH/HQMB	1	1	NRR/DRPM/PECB	1	1
NRR/DSSA/SPLB	1	1	RES/DET/EIB	1	1
RGN3 FILE 01	1	1			
EXTERNAL: L ST LOBBY WARD	1	1	LITCO BRYCE, J H	1	1
NOAC POORE, W.	1	1	NOAC QUEENER, DS	1	1
NRC PDR	1	1	NUDOCS FULL TXT	1	1

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 22

AO4

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5901



December 11, 1998

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/98-031-01, "Potential Common Mode Failure of Residual Heat Removal Pumps Due to Use of Inaccurate Values".

The following commitment was identified in this submittal:

- Replace flow instruments and calibrate using new setpoints.

Sincerely,

A handwritten signature in cursive script, appearing to read "John R. Sampson".

J. R. Sampson
Site Vice President

/mbd
Attachment

c: J. L. Caldwell (Acting), Region III
R. P. Powers
P. A. Barrett
J. B. Kingseed
R. Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector

9812150143 981211
PDR ADOCK 05000315
S PDR