

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9812230144      DOC.DATE: 98/12/16    NOTARIZED: NO                  DOCKET #  
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M    05000315  
AUTH.NAME                  AUTHOR AFFILIATION  
SAMPSON,J.R.                Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
RECIP.NAME                  RECIPIENT AFFILIATION .  
                               Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-050-00 re ancillary equipment installed in ice condenser not designed to withstand design basis accident/earthquake loads. Listed commitments identified in submittals.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2  
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

**NOTES:**

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-3 PD	1 1	STANG, J	1 1
INTERNAL: AEOD/SPD/RAB	2 2	AEOD/SPD/RRAB	1 1
<u>FILE CENTER</u>	1 1	NRR/DE/ECGB	1 1
NRR/DE/EELB	1 1	NRR/DE/EMEB	1 1
NRR/DRCH/HICB	1 1	NRR/DRCH/HOHB	1 1
NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
NRR/DSSA/SPLB	1 1	RES/DET/EIB	1 1
RGN3 FILE 01	1 1		
EXTERNAL: L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
NRC PDR	1 1	NUDOCS FULL TXT	1 1

**NOTE TO ALL "RIDS" RECIPIENTS:**

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 22

C  
A  
T  
E  
G  
O  
R  
Y  
1  
  
D  
O  
C  
U  
M  
E  
N  
T



Indiana Michigan  
Power Company  
Cook Nuclear Plant  
One Cook Plant  
Bridgman, MI 49106  
616 465 5901



December 16, 1998

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Operating License DPR-58  
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/98-050-00, "Ancillary Equipment Installed in Ice Condenser Not Designed to Withstand Design Basis Accident/Earthquake Loads."

The following commitments were identified in this submittal:

- A design change has been developed to upgrade the supports/restraints for certain large or concentrated areas of electrical equipment located inside the ice condenser. Installation of the design change will be completed prior to plant restart.
- Design criteria have been developed for the ice condenser ancillary equipment. These criteria will be incorporated into the Updated Final Safety Analysis Report.

Sincerely,

A handwritten signature in cursive script that reads 'John R. Sampson'.

J. R. Sampson  
Site Vice President

/mbd

Attachment

9812230144 981216  
PDR ADOCK 05000315  
S PDR

1/1  
IE 22

c: J. L. Caldwell (Acting), Region III  
R. P. Powers  
P. A. Barrett  
J. B. Kingseed  
R. Whale  
D. Hahn  
Records Center, INPO  
NRC Resident Inspector

