



October 11, 1978

PRN-LI-78-295

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-78-12  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: SEPTEMBER 27, 1978

CYCLE 5  
CORE LOADING PATTERN

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide prompt notification of the subject occurrence.

Very truly yours,

*C. D. Woody*  
A. D. Schmidt  
Vice President  
Power Resources

**REGULATORY DOCKET FILE COPY**

WAK/mld

Attachment

cc: Robert Lowenstein, Esquire  
Director, Office of Inspection and Enforcement (40)  
✓ Director, Office of Management Information and  
Program Control (3)

**REGULATORY DOCKET FILE COPY**

7810200114

*1002  
5/1*



10-11-68