

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7909190478 DOC. DATE: 79/09/04 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light Co 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light Co 05000251
 AUTH. NAME AUTHOR AFFILIATION
 YAEGER, H. E. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: RO 250-79-26: failure to install two supports for three
 blowdown lines between Unit 3 containment penetration &
 first isolation valve of containment. Design being evaluated.

DISTRIBUTION CODE: M007S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: LER (Backfit)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
INTERNAL:	01 REG FILE	1 1	02 NRC PDR	1 1
	04 I&E	2 2	MPA	1 1
	NSIC	1 1	S HANAUER	1 1
EXTERNAL:	03 LPDR	1 1		

SEP 21 1979

TOTAL NUMBER OF COPIES REQUIRED: LTTR 8 ENCL 0

KTB
A04

[illegible][illegible]

P.O. BOX 3100 DALLAS, TEXAS 75201

Nuclear Plant Supervisor, KEY, JOHN, HARTMAN,
BOCK, LIT, WAW, JIM, JEN, WAW, A. KED, NTA,
DWH, PAUL, JSU, BMJ, CLY, QA, JEN,
NRC RESIDENT INSPECTOR

AUS. JIB. CON. HAS

Date _____
Time _____ By _____

PTP-QC-79-176
Turkey Point Plant
August 31, 1979

Mr. J. P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Atlanta, Georgia 30303

Mr. H. E. Vaeger, Plant Manager
Turkey Point Plant - BFR 31 and 41
Florida Power and Light Company
Miami, Florida

MEMO FOR FACSIMILE TRANSMISSION TO CONFIRM
REPORTABLE OCCURRENCE 250-79-26

CONNECTIVE ACTION - The manual blowdown isolation valve on each line inside containment has been closed to preclude any concern regarding the improperly supported section of outside containment. Design review and evaluation shows that installation of one on each line outside containment will restore full support requirements. This effort is being expeditiously pursued.

H. E. Yaeger
Plant Manager

HEY:JKH:SR

7909190 478

