

Golda Mullinex
P.O. BOX 529100, MIAMI, FL 33152

USNRC REGION II
ATLANTA, GEORGIA

79 SEP 7 11:03



August 31, 1979

PRN-LI-79-321

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-79-24
TURKEY POINT UNIT 3
DATE OF OCCURRENCE: AUGUST 2, 1979

TECHNICAL SPECIFICATION 3.14.2.b.1
WEST FIRE PUMP

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30-day notification of the subject occurrence.

Very truly yours,

Ed Woody
A. D. Schmidt
Vice President
Power Resources

MAS/cph

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and Program Control (3)
Robert Lowenstein, Esquire
File 933.1TP

*A002
5/1*

7909260290

