



December 28, 1979  
PRN-LI-79-462

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-79-36  
TURKEY POINT UNIT 3  
DATE OF OCCURRENCE: NOVEMBER 28, 1979

AUXILIARY FEED PUMP A

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30-day notification of the subject occurrence.

Very truly yours,

*for J.R. Bensen*  
A. D. Schmidt  
Vice President  
Power Resources

MAS/cph

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Director, Office of Management Information and  
Program Control (3)  
Robert Lowenstein, Esquire  
File 933.1TP

8002040

5  
A002  
50511  
PEOPLE...SERVING PEOPLE