


8005120427



FLORIDA POWER & LIGHT COMPANY

April 30, 1980

PRN-LI-80-176

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-80-05
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: MARCH 31, 1980

TECHNICAL SPECIFICATION 3.1.3
PROCESS RADIATION MONITORS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30-day notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
Vice President
Power Resources

MAS/pa

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)
Harold F. Reis, Esquire
File 933.1 TP

A002
S
1/1



Handwritten marks and scribbles in the top right corner.

Handwritten marks and scribbles in the bottom left corner.