



May 21, 1980

PRN-LI-80-204

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-80-07
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: MAY 7, 1980

4A MAIN STEAM CHECK VALVE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide prompt notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
Vice President
Power Resources

MAS/KMS/pa

Attachment

cc: Director, Office of Inspection and Enforcement (40)
Director, Office of Management Information and
Program Control (3)
Harold F. Reis, Esquire
File 933.1 TP

A002
S
1/1

S 8006030 454



10

1. 1000