



May 30, 1980

PRN-LI-80-214

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-80-3
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: MAY 30, 1980

TECHNICAL SPECIFICATION 3.8.1
MAIN STEAM SAFETY VALVE
UPDATE REPORT NO. 1

The attached Licensee Event Report is being submitted to update our initial response dated March 17, 1980.

Very truly yours,

A. D. Schmidt
Vice President
Power Resources

MAS/pa

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)
Harold F. Reis, Esquire
File 933.1

A002
S
1/1

8006190258

S

8006160 23