

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8012020474 DOC. DATE: 80/11/12 NOTARIZED: NO DOCKET #
 FACIL: 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 PACE, P.L. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Region 2, Atlanta, Office of the Director

SUBJECT: LER 80-012/03L-0: on 801013, excessive leakage past primary
 packing in charging pump 4A caused pump to be removed from
 svc. Caused by loose packing. Packing replaced.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME		COPIES	
			LITR	ENCL			LITR	ENCL
ACTION:	VARGA, S.	04	3	3				
INTERNAL:	A/D COMP&STRU06		1	1	A/D ENV TECH 07		1	1
	A/D MATLI & QU08		1	1	A/D OP REACT009		1	1
	A/D PLANT SYS10		1	1	A/D RAD PROT 11		1	1
	A/D SFTY ASSE12		1	1	A/D TECHNOLOG13		1	1
	ACC EVALI BR 14		1	1	AEOD		2	2
	ASLBP/J. HARD		1	1	AUX SYS BR 15		1	1
	CHEM ENG BR 16		1	1	CONT SYS BR 17		1	1
	CORE PERF BR 18		1	1	D/DIR, HUM FAC19		1	1
	DIR, ENGINEER120		1	1	DIR, HUM FACI S21		1	1
	DIR, SYS INTEG22		1	1	EFF TR SYS BR23		1	1
	EQUIP QUALI BR25		1	1	GEOSCIENCES 26		1	1
	I&C SYS BR 29		1	1	I&E 05		2	2
	JORDAN, E./IE:		1	1	LIC GUID BR 30		1	1
	LIC QUALI BR 31		1	1	MATLI ENG BR 32		1	1
	MECH ENG BR 33		1	1	MPA		3	3
	NRC PDR 02		1	1	OP EX EVALI BR34		3	3
	OR ASSESS BR 35		1	1	POWER SYS BR 36		1	1
	RAD ASSESS BR39		1	1	REACT SYS BR 40		1	1
	REG FILE 01		1	1	RELI & RISK A 41		1	1
	SFTY PROG EVA42		1	1	STRUCT ENG BR44		1	1
	SYS INTERACI B45		1	1				
EXTERNAL:	ACRS	46	16	16	LPDR	03	1	1
	NSIC	05	1	1	TERA: DOUG MAY		1	1

DEC 3 1980

TOTAL NUMBER OF COPIES REQUIRED: LITR 69 ENCL 69

L.T.

