

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L T P S 3 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 7 3 14 15 25 26 30 31 32 33 34 35 36 37 38 39

CCNT
 01
 7 3

REPORT SOURCE L 6 0 5 0 0 0 2 5 0 7 1 1 0 3 8 0 3 1 2 0 3 8 0 9
 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
 012 During power operation, Control Rod M-8 (in Control Bank D) dropped.
 013 This is reportable pursuant to TS 6.9.2.b.2. Public health and safety
 014 was not affected. This occurrence is within the bounds of the analysis
 015 presented in FSAR Section 14.1.4. This is the first reportable occurrence
 016 of this type.
 017
 018
 019

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 09 R B 11 E 12 X 13 C O N R O D 14 Z 15 Z 16
 7 8 10 11 12 13 14 15 16 17 18 19 20 21 22

17 LEA/RO REPORT NUMBER 80 21 22
 18 EVENT YEAR 80 21 22
 19 SEQUENTIAL REPORT NO. 0 2 2 23 24 25 26
 20 OCCURRENCE CODE 0 3 27 28 29
 21 REPORT TYPE L 30 31
 22 REVISION 0 32

ACTION TAKEN E 12 Z 19 33 34
 FUTURE ACTION Z 19 35 36
 EFFECT ON PLANT Z 20 37 38
 SHUTDOWN METHOD Z 21 39 40
 HOURS 0 0 0 41 42 43
 ATTACHMENT SUBMITTED N 22 44 45
 APPROX. FORM SUB. N 24 46 47
 PRIME COMP. SUPPLIER N 25 48 49
 COMPONENT MANUFACTURER W 1 2 0 26 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
 110 Subsequent to an investigation to determine the cause of the rod drop, the
 111 rod was retrieved and the unit was returned to full power in accordance
 112 with approved procedures. The cause of the occurrence could not be
 113 determined.
 114
 115

116 FACILITY STATUS 23 12 13
 117 % POWER 0 7 9 29 30
 118 OTHER STATUS NA 31 32
 119 METHOD OF DISCOVERY A 33 34
 120 DISCOVERY DESCRIPTION Operator observation 35 36

121 ACTIVITY CONTENT 37 38
 122 RELEASED OR RELEASE Z 39 40
 123 AMOUNT OF ACTIVITY NA 41 42
 124 LOCATION OF RELEASE NA 43 44

125 PERSONNEL EXPOSURES NUMBER 0 0 0 37 38
 126 TYPE Z 39 40
 127 DESCRIPTION NA 41 42

128 PERSONNEL INJURIES NUMBER 0 0 0 43 44
 129 DESCRIPTION NA 45 46

130 LOSS OF OR DAMAGE TO FACILITY TYPE Z 47 48
 131 DESCRIPTION NA 49 50

132 PUBLICITY ISSUED N 49 50
 133 DESCRIPTION NA 51 52

134 NRC USE ONLY
 135

NAME OF PREPARER P. L. Pace PHONE: (305) 552-3801

8101050 542