

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 FLTPS3 2 d0-000000-00 3 41111 4 ... 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 38 39

CCNT 01 REPORT SOURCE L 6 0510002510 7 121280 3 122380 9

DOCKET NUMBER 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 Quality Control surveillance activities and observations by a chemistry

03 technician revealed that a motor operated valve in the sample line from

04 3A steam generator (S/G) was closed. This precluded continuous monitoring

05 of that generator (via PRMS Ch. 19) as required by TS 3.9.1.i during

06 blowdown operations. During this period, the 3B & 3C S/G liquid samples

07 and non-condensable gas from all 3 S/Gs via the steam jet air ejector

08 exhausts were continuously monitored.

09 MC 11 A 12 X 13 ZZZZZ 14 Z 15 Z 16

SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 13 14 COMPONENT CODE 15 16 COMP. SUBCODE 17 18 VALVE SUBCODE 19 20

17 80 1 027 01 T 0

LER/RO REPORT NUMBER 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 25 26 OCCURRENCE CODE 27 28 REPORT TYPE 29 30 REVISION NO. 31 32

ACTION TAKEN EH 18 19 Z 20 Z 21 0000 22 N 23 N 24 Z 25 Z999 26

ACTION FUTURE TAKEN 33 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 38 ATTACHMENT SUBMITTED 39 40 NPRO-4 FORM SUB. 41 PRIME COMP. SUPPLIER 42 43 COMPONENT MANUFACTURER 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The root cause of the occurrence was inadvertent closing of the valve while

11 maintenance was performed on the valve operator. Blowdown from the 3A

12 steam generator was terminated pending completion of repairs to the motor

13 operator. The maximum duration of interrupted flow was 29 hours. No

14 activity above background was present during the period.

15 E160 23 160 29 NA 30 B 31 Quality Control surveillance 32

FACILITY STATUS 3 4 % POWER 5 6 OTHER STATUS 30 31 METHOD OF DISCOVERY 32 33 DISCOVERY DESCRIPTION 34 35

16 Z 33 Z 34 NA 35 NA 36

ACTIVITY CONTENT 3 4 RELEASED OF RELEASE 5 6 AMOUNT OF ACTIVITY 35 36 LOCATION OF RELEASE 36 37

17 0000 37 Z 38 NA 39

PERSONNEL EXPOSURES NUMBER 3 4 TYPE 5 6 DESCRIPTION 39 40

18 0000 40 NA 41

PERSONNEL INJURIES NUMBER 3 4 DESCRIPTION 41 42

19 Z 43 NA 44

LOSS OF OR DAMAGE TO FACILITY TYPE 3 4 DESCRIPTION 43 44

20 N 45 NA 46

PUBLICITY ISSUED 3 4 DESCRIPTION 45 46

20 N 46 NA 47

NAME OF PREPARER P.L. Pace PHONE: (305) 552-3801

810 1130382

