

SUMMARY OF OPERATING EXPERIENCE

DOCKET NO. 50 - 250

UNIT Turkey Point
Unit No. 3

DATE January 10, 1981

COMPLETED BY V. T. Chilson

TELEPHONE (305) 552-3824

REPORT MONTH DECEMBER, 1980

Unit No. 3 operated at approximately 100% R.P. after the unit was returned to service on December 6, 1980, except for load reductions of December 8-9 and 9-11, 1980. Refer to "Unit Shutdowns and Power Reductions" section of December, 1980, Operating Status Report for additional information.

Major Safety-related maintenance activities performed during the month included:

Inspections and requirements of IE Bulletins and NUREG-0578 are continuing.

Florida Power & Light Company commitments for NUREG-0578 implementation are continuing. Refer to correspondence between FPL and NRC for additional information.

Completed repair of leaking tube plugs in steam generator No. 3B.

Completed inspection of reactor coolant pump No. 3B shaft seals.

810 1210418

10-1-77

10-1-77

10-1-77

SUMMARY OF OPERATING EXPERIENCE

DOCKET NO. 50 - 251

UNIT Turkey Point
Unit No. 4

DATE January 10, 1981

COMPLETED BY V. T. Chilson

TELEPHONE (305) 552-3824

REPORT MONTH DECEMBER, 1980

Unit No. 4 was removed from service for scheduled refueling, maintenance, and inspections. (Continued from previous month). Refer to "Unit Shutdowns and Power Reductions" section of the December, 1980, Operating Status Report for additional information.


Major Safety-related maintenance activities performed during the month included:

Inspections and requirements of IE Bulletins and NUREG-0578 in progress.

Florida Power & Light Company commitments for NUREG-0578 implementation are continuing. Refer to correspondence between FPL and NRC for additional information.

Completed Steam Generator Tube Inspection Program.

Installed eighteen new fuel assemblies.



SUMMARY OF OPERATING EXPERIENCE

DOCKET NO. 50 - 335

UNIT St. Lucie
Unit No. 1

DATE January 10, 1981

COMPLETED BY V. T. Chilson

TELEPHONE (305) 552-3824

REPORT MONTH DECEMBER, 1980

Unit operated at approximately 100% R.P. during month. Refer to "Unit Shutdowns and Power Reductions" section of the December, 1980, Operating Status Report for additional information.

Major Safety-related maintenance activities performed during the month included:

Inspections and requirements fo IE Bulletins and NUREG-0578 are continuing.

Florida Power & Light Company commitments for NUREG-0578 implementation are continuing.
Refer to correspondence between FPL and NRC for additional information.

