

RECEIVED DISTRIBUTION
SERVICES UNIT

1981 JAN 2 PM 1 17

US NRC
DISTRIBUTION SERVICES
BRANCH



January 16, 1981

PRN-LI-81-28


Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-81-2
TURKEY POINT UNIT 3
DATE OF OCCURRENCE: JANUARY 3, 1980
TECHNICAL SPECIFICATION 3.6.b.4
BORIC ACID FLOWPATH

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide prompt notification of the subject occurrence.

Very truly yours,


A.D. Schmidt
Vice President
Power Resources

PLP/mbd

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

A002
S
1/1

5
8102080 536

0805012