

86-030-03L

USNRC REGION II  
ATLANTA, GEORGIA



FLORIDA POWER & LIGHT COMPANY

30 DEC 24 A10:10

December 19, 1980

PRN-LI-80-532

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-80-24  
TURKEY POINT UNIT 3  
DATE OF OCCURRENCE: NOVEMBER 19, 1980  
TECHNICAL SPECIFICATION 6.9.2.b  
FEEDWATER FLOW CONTROL VALVE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.


Very truly yours,

A.D. Schmidt  
Vice President  
Power Resources

PLP/md

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Harold F. Reis, Esquire  
File 933.1 TP



A002  
S.11

OFFICIAL COPY

S

8102250 671

