

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8104080298 DOC. DATE: 81/04/02 NOTARIZED: NO DOCKET # 05000250  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light Co. 05000251  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light Co.  
 AUTH. NAME: UHRIG, R.E. AUTHOR AFFILIATION: Florida Power & Light Co.  
 RECIP. NAME: EISENHUT, D.G. RECIPIENT AFFILIATION: Division of Licensing

SUBJECT: Informs that emergency operations facility conceptual design descriptions will be provided by 810601. Requirement re min. staffing for emergencies will be difficult to meet. Appropriate personnel do not live close enough to plant.


DISTRIBUTION CODE: A046S COPIES RECEIVED: LTR 3 ENCL 0 SIZE: 1  
 TITLE: Response to NUREG-0737/NUREG-0660 TMI Action Plan Rgmts (OL's)

## NOTES:

ACTION:	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME		COPIES	
			LTTR	ENCL			LTTR	ENCL
	VARGA, S.	05	7					
INTERNAL:	A/D C&C SYS	27	1		A/D C&S ENG	22	1	
	A/D FOR TECH	32	1		A/D GEN PROJ	31	1	
	A/D LICENS	16	1		A/D M&G ENG	23	1	
	A/D OP REACT	15	1		A/D PLANT SYS	25	1	
	A/D RAD PROT	26	1		A/D SAFETY AS	17	1	
	DEP DIR, DHFS	29	1		DIR, EM PREP	33	1	
	DIRECTOR, DE	21	1		DIRECTOR, DHFS	28	1	
	DIRECTOR, DL	14	1		DIRECTOR, DSI	24	1	
	DIRECTOR, DST	30	1		I&E	12	2	
	OELD		1		OR ASSESS BR	18	3	
	PDR	02	1		RAD ASMT BR		1	
	REG FILE	01	1					
EXTERNAL:	ACRS	34	16	16	LPDR	03	1	
	NSIC	04	1					

APR 8 1981

TOTAL NUMBER OF COPIES REQUIRED: LTTR 51 ENCL 2





FLORIDA POWER & LIGHT COMPANY

April 2, 1981  
L-81-147

Director of Nuclear Reactor Regulation  
Attention: Mr. Darrell G. Eisenhut, Director  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mr. Eisenhut:

Re: Turkey Point Units 3 & 4  
Docket Nos. 50-250 & 50-251  
Post-TMI Requirements for the  
Emergency Operations Facility

Florida Power & Light Company has reviewed Enclosure 1 of your letter dated February 18, 1981. Facility Conceptual design descriptions will be provided by June 1, 1981 as required.

The requirement regarding minimum staffing for emergencies (Table III A.1.2-1) will prove exceedingly difficult to meet due to the lack of appropriate personnel living in areas close enough to the plant which would allow them to respond in the required time. We will discuss the staffing situation more completely in our June 1, 1981 submittal.

Very truly yours,


*J. A. De Mastry*  
*jr*

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/JEM/mbd

Attachments

cc: Mr. James P. O'Reilly, Region II  
Harold F. Reis, Esquire



A046  
S  
3/0

810.40.80298

p



1  
2  
3

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.



.....

.....

.

.

.

.

.

.

.