



March 20, 1981

PRN-LI-81-135

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-81-03
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: February 18, 1981

RCS LEAKAGE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
Vice President
Power Resources

PLP/bc

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1



A002
S
11/1

S 8104130187



11/11/11