


April 8, 1981

PRN-LI-81-175

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-80-07
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: MAY 7, 1980
4A MAIN STEAM CHECK VALVE
UPDATE REPORT NO. 1



The attached Licensee Event Report is being submitted to update our initial report of May 21, 1980.

Very truly yours,

A.D. Schmidt
for A.D. Schmidt
Vice President
Power Resources

PLP/mbd

Attachment

cc: Director, Office of Inspection and Enforcement (40)
Harold F. Reis, Esquire
File 933.1 TP

*A002
S.1*

8104270312

S

