

May 29, 1981

PRN-LI-81-258

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-81-10

TURKEY POINT UNIT 3

DATE OF OCCURRENCE: MAY 1, 1981

TECHNICAL SPECIFICATION 3.4.4.1

"3A" COMPONENT COOLING WATER PUMP BREAKER

The attached Licensee Event Report is being submitted in accordance with
Technical Specification 6.9 to provide 30 day notification of the subject
occurrence.


Very truly yours,

A.D. Schmidt
Vice President
Power Resources

PLP/cab

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP



810608 0382

6

A002
S11

