



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

March 26, 1980

BBS LTR #80-256

Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Ill 60137

Reportable Occurrence "Update Report" #79-30-03X-1, Docket #050-249, is being submitted to your office to supplement Licensee Event Report #79-30-03L-0, which concerned the substantial loss of position indication for CRD H-9. The "Update Report" addresses the cause and corrective actions for the loss of position indication. This event was reported to you under Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation.

B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:lbg

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

A002
5 1/1

8004080 456

gmr

