

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)


ACCESSION NBR: 8206010335 DOC. DATE: 82/05/24 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 UHRIG, R.E. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 VARGA, S.A. Operating Reactors Branch 1


SUBJECT: Advises that util 800613 & 810227 ltrs committed to meeting requirements of TMI Action Plan Item II.K.3.3, "Reporting Safety & Relief Valve Failures & Challenges," in response to NRC 820416 ltr.

DISTRIBUTION CODE: A0468 COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1
 TITLE: Response to NUREG -0737/NUREG-0660 TMI Action Plan Rgmts (OL's)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	ORB #1 BC 01	7 7		
INTERNAL:	ELD/HDS4	1 0	IE/DEP DIR 33	1 1
	IE/DEP EPDS	1 1	IE/DEP/EPLB	3 3
	NRR/DE DIR 21	1 1	NRR/DE/ADCSE 22	1 1
	NRR/DE/ADMGE 23	1 1	NRR/DHFS DIR 28	1 1
	NRR/DHFS/DEPY 29	1 1	NRR/DL DIR 14	1 1
	NRR/DL/ADL 16	1 1	NRR/DL/ADOR 15	1 1
	NRR/DL/ADSA 17	1 1	NRR/DL/ORAB 18	3 3
	NRR/DSI DIR 24	1 1	NRR/DSI/ADDPS 25	1 1
	NRR/DSI/ADRP 26	1 1	NRR/DSI/ADRS 27	1 1
	NRR/DSI/AEB	1 1	NRR/DSI/ETSB	1 1
	NRR/DSI/RAB	1 1	NRR/DST DIR 30	1 1
	NRR/DST/ADGP 31	1 1	NRR/DST/ADT 32	1 1
	<u>REG FILE</u> 04	1 1	RGN2	1 1
EXTERNAL:	ACRS 34	10 10	FEMA-REP DIV	1 1
	INPO, J. STARNES	1 1	LPDR 03	1 1
	NRC PDR 02	1 1	NSIC 05	1 1
	NTIS	1 1		





May 24, 1982
L-82-207

Office of Nuclear Reactor Regulation
Attention: Mr. Steven A. Varga, Chief
Operating Reactors Branch #1
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Varga:

Re: Turkey Point Units 3 & 4
Docket Nos. 50-250 and 50-251
Post-TMI Requirements
Reporting Safety and Relief
Valve Failures and Challenges

In your letter of April 16, 1982 you requested that Florida Power and Light Company commit to the requirements of TMI Action Plan Item II.k.3.3, "Reporting Safety and Relief Valve Failures and Challenges". You additionally stated that our letter of February 27, 1981 (L-81-84) did not commit to meeting all of the reporting requirements for this issue.

Our letter L-80-186 dated June 13, 1980 to Mr. Eisenhut contained our commitment that "FPL intends to comply with the requirements of Item II.k.3.3" for Turkey Point Units 3 & 4. Our letter of February 27, 1981 was submitted to Mr. Eisenhut as a consequence of our commitment to meet the reporting requirements.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/PKG/mbd

cc: J.P. O'Reilly, Region II
Harold F. Reis, Esquire

A046
5
1/1

82060 10335

P

