

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8210270253 DOC.DATE: 82/10/21 NOTARIZED: NO DOCKET #  
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH.NAME AUTHOR AFFILIATION  
 UHRIG,R.F. Florida Power & Light Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 DIGGS,R.M. License Fee Management Branch

SUBJECT: Forwards util 821012 ltr containing payment of license amend  
 fee re redundancy in RHR sys requested in NRC 820816 ltr.

DISTRIBUTION CODE: M008S COPIES RECEIVED:LTR \_/ ENCL \_/ SIZE:\_/\_/\_/\_/\_/\_/\_/\_  
 TITLE: License Fees

## NOTES:

	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL
	NRR ORB1 BC 04		1 1		GROTENHUIS,M 01		1 1
INTERNAL:	ADM/LFMB 06		1 1	REG FILE	04		1 1
EXTERNAL:	LPDR 03		1 1	NRC PDR 02			1 1
	NTIS 05		1 1				

*[Illegible handwritten text]*



October 21, 1982  
L-82-451

Mrs. Reba M. Diggs  
Facilities Program Coordinator  
License Fee Management Branch  
Office of Administration  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mrs. Diggs:

Re: Turkey Point Units 3 & 4  
Docket Nos. 50-250 & 50-251  
Proposed License Amendment  
Redundancy in the Residual  
Heat Removal System.

Enclosed please find a copy of our October 12, 1982 (L-82-437) letter in which payment of the requested amount in your August 16, 1982 letter was made.

It appears that your letter of October 15, 1982 and our letter of October 12, 1982 "crossed in the mail". Please notify us if you have not received our October 12, 1982 letter.

Very truly yours

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/SAV/cab

M008

8210270253 821021  
PDR ADOCK 05000250  
P PDR

