

REVISED COPY  
UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-250  
UNIT NAME Turkey Point Unit #3

DATE November 16, 1987

COMPLETED BY N. W. Grant

TELEPHONE (305) 694-4432

REPORT MONTH October 1987

No.	Date	Type <sup>1</sup>	Duration (Hours)	Reason <sup>2</sup>	Method of Shutting Down Reactor <sup>3</sup>	Licensee Event Report #	System Code <sup>4</sup>	Component Code <sup>5</sup>	Cause & Corrective Action to Prevent Recurrence
08	870925	F	745.0	A	1		CF	PUMPXX	Unit 3 remained shutdown to repair various items including a leak on the 3 B RHR pump, charging line discharge flow control valve bonnet leak, a seal table leak and cabling for the 3 A RHR pump motor.

**1**  
F Forced  
S Scheduled

**2**  
Reason  
A - Equipment Failure (Explain)  
B - Maintenance or Test  
C - Refueling  
D - Regulatory Restriction  
E - Operator Training & License Examination  
F - Administrative  
G - Operational Error (Explain)  
H - Other (Explain)

**3**  
Method  
1 - Manual  
2 - Manual Scram  
3 - Automatic Scram  
4 - Continued  
5 - Load Reduction  
9 - Other (Explain)

**4**  
Exhibit G- Instructions  
for Preparation of Data  
Entry Sheets Licensee  
Event Report (LER) File  
(NUREG-0161)

**5**  
Exhibit 1- Same Source

REVISED COPY  
UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-251

UNIT NAME Turkey Point Unit #4

DATE November 16, 1987

COMPLETED BY N. W. Grant

REPORT MONTH October 1987

TELEPHONE (305) 694-4432

No.	Date	Type <sup>1</sup>	Duration (Hours)	Reason <sup>2</sup>	Method of Shutting Down Reactor <sup>3</sup>	Licensee Event Report #	System Code <sup>4</sup>	Component Code <sup>5</sup>	Cause & Corrective Action to Prevent Recurrence
05	871012	F	467.2	H	1		XX	VALVEX	Unit #4 was shutdown as a precautionary measure for a hurricane warning. The unit remained shutdown for the remainder of the period for repair of miscellaneous items including a purge valve actuator and a leaking PORV.

1  
F Forced  
S Scheduled

2  
Reason  
A - Equipment Failure (Explain)  
B - Maintenance or Test  
C - Refueling  
D - Regulatory Restriction  
E - Operator Training & License Examination  
F - Administrative  
G - Operational Error (Explain)  
H - Other (Explain)

3  
Method  
1 - Manual  
2 - Manual Scram  
3 - Automatic Scram  
4 - Continued  
5 - Load Reduction  
9 - Other (Explain)

4  
Exhibit G- Instructions  
for Preparation of Data  
Entry Sheets Licensee  
Event Report (LER) File  
(NUREG-0161)

5  
Exhibit 1 - Same Source



REVISED COPY  
UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-389  
UNIT NAME St. Lucie Unit #2  
DATE November 16, 1987

COMPLETED BY N. W. Grant

REPORT MONTH October 1987

TELEPHONE (305) 694-4432

No.	Date	Type <sup>1</sup>	Duration (Hours)	Reason <sup>2</sup>	Method of Shutting Down Reactor <sup>3</sup>	Licensee Event Report #	System Code <sup>4</sup>	Component Code <sup>5</sup>	Cause & Corrective Action to Prevent Recurrence
10	871002	S	696.9	C	1		RC	FUELXX	Unit 2 was shutdown for refueling and scheduled maintenance.

1  
F Forced  
S Scheduled

2  
Reason  
A - Equipment Failure (Explain)  
B - Maintenance or Test  
C - Refueling  
D - Regulatory Restriction  
E - Operator Training & License Examination  
F - Administrative  
G - Operational Error (Explain)  
H - Other (Explain)

3  
Method  
1 - Manual  
2 - Manual Scram  
3 - Automatic Scram  
4 - Continued  
5 - Load Reduction  
9 - Other (Explain)

4  
Exhibit G- Instructions  
for Preparation of Data  
Entry Sheets Licensee  
Event Report (LER) File  
(NUREG-0161)

5  
Exhibit 1 - Same Source

