

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8801150220 DOC.DATE: 88/01/12 NOTARIZED: NO DOCKET #  
 FACIL:50-000 Generic Docket 05000000  
 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co. 05000335  
 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co. 05000389  
 AUTH.NAME AUTHOR AFFILIATION  
 WOODY,C.D. Florida Power & Light Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 GRACE,J.N. Region 2, Ofc of the Director

SUBJECT: Advises that response to NRC Bulletin 87-002 will be submitted by 880212, per 880111 telcon.

DISTRIBUTION CODE: IE11D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1  
 TITLE: Bulletin Response (50 DKT)

### NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-2 LA	1 0	PD2-2 PD	1 1
MCDONALD, D	1 1	TOURIGNY, E	1 1
INTERNAL: AEOD/DOA	1 1	AEOD/DSP	1 1
AEOD/DSP/TPAB	1 1	NRR/DEST/ADE	1 1
NRR/DEST/ADS	1 1	NRR/DEST/MEB	1 1
NRR/DOEA/EAB	1 1	NRR/DOEA/GCB	1 1
NRR/DREP/EPB	1 1	NRR/PMAS/ILRB	1 1
REG FILE 02	1 1	RES/DE/EIB	1 1
RGN2 FILE 01	1 1		
EXTERNAL: LPDR	2 2	NRC PDR	1 1
NSIC	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 21 ENCL 0

R  
I  
D  
S  
/  
A  
D  
D  
S  
  
R  
I  
D  
S  
/  
A  
D  
D  
S

**FPL**

JANUARY 12 1988

L-88-14

Dr. J. Nelson Grace  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta St., N.W., Suite 2900  
Atlanta, GA 30323


Dear Dr. Grace:

Re: St. Lucie Units 1 and 2  
Docket Nos. 50-335 and 50-389  
Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
NRC Bulletin 87-02: Fastner Testing to Determine  
Conformance with Applicable Material Specifications

On January 11, 1988, a telephone conference call was held between Florida Power & Light (FPL) and the NRC Region II Staff to discuss an extension in FPL's response to NRC Compliance Bulletin No. 87-02. FPL requested a one month delay from the original response schedule of January 12, 1988. The new response schedule as agreed is February 12, 1988. The reason for delay is that the verification and validation of test results has not been completed.

Should there be questions, please contact us.

Very truly yours,



C. O. Woody  
Executive Vice President

COW/MSD/gp

cc: Document Control Desk, USNRC  
Senior Resident Inspector, USNRC, St. Lucie Plant  
Senior Resident Inspector, USNRC, Turkey Point Plant

MSD/011.BUL

TELL  
1/0

an FPL Group company

