

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8703250427 DOC. DATE: 87/03/18 NOTARIZED: NO DOCKET #
 FACIL: 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHORITY AFFILIATION
 WOODY, C. O. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: IAEA RO 87-02: on 870315, informed NRC of necessity of removing IAEA seals on equipment hatch & missile shields to perform insp & maint activities. Surveillance of reactor maintained by three remaining seals on reactor head.

DISTRIBUTION CODE: S006D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Part 75 IAEA Safeguards Data

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PWR-A PD2 LA	1 0	PWR-A PD2 PD	1 0
	McDONALD, D	1 1		
INTERNAL:	AEOD/PTB	1 0	IE/DI/ORPB	1 1
	NMSS/SGMC	6 6	NRR PWR-B SSPD	1 1
	<u>REG FILE</u> 01	1 1	RGN2	1 1
EXTERNAL:	LPDR	1 0	NRC PDR	1 0

TO: DIRECTOR, FBI
FROM: SAC, NEW YORK
SUBJECT: [Illegible]
[Illegible text block]

Re New York letter to Bureau dated 1/15/64.
[Illegible text block]

Enclosed for the Bureau are two copies of a letterhead memorandum (LHM) dated and captioned as above.

TO:	FROM:	SUBJECT:
Director, FBI	SAC, New York	[Illegible]
Assistant Attorney General, Department of Justice	SAC, New York	[Illegible]
Chief of Police, New York City	SAC, New York	[Illegible]
Chief of Police, New York State	SAC, New York	[Illegible]
Chief of Police, New York County	SAC, New York	[Illegible]



MARCH 18 1987

L-87-135

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555


Gentlemen:

Re: Turkey Point Unit 4
Docket No. 50-251
IAEA Reportable Occurrence 87-02

This letter and its attachment provide written notification in accordance with NRC letter dated June 3, 1986 of IAEA Reportable Occurrence 87-02.

Should additional information be required, please contact us.

Very truly yours,


C. O. Woody
Group Vice President
Nuclear Energy

COW/TCG/pm

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator, Region II, USNRC
Mr. Gene Sparks, NRC Washington, M.S. 88155
Senior Resident Inspector, USNRC, Turkey Point Plant

8703250427 870318
PDR ADDCK 05000251
S PDR

Soole
11

THE UNIVERSITY OF CHICAGO
LIBRARY

1964

1964

1964

1964

1964

1964

1964

1964

1964

1964

1964

IAEA REPORTABLE OCCURRENCE 87-02

Summary of Events:

At 1750 on March 15, 1987, Mr. Gene Sparks, NRC Office of Nuclear Material Safety and Safeguards, was informed of the necessity of removing the IAEA seals on the equipment hatch and on the missile shields. This was required in order to perform inspection and maintenance activities in the reactor head area because of a buildup of boric acid in that area resulting from a leak at an instrumentation penetration pressure boundary seal. The seals on the equipment hatch were cut at 1900 on March 15, and the seals on the missile shields were removed at approximately 1300 on March 16.

Results:

- 1) There are three remaining seals on the reactor head. The IAEA will be notified as soon as possible if these need to be removed.
- 2) All four of the IAEA seals on the equipment hatch were removed and retained by FPL.
- 3) Both of the IAEA seals on the missile shields were removed and retained by FPL.

Conclusion:

The continuous surveillance of the reactor is being maintained by the three remaining seals on the reactor head.

NEW YORK

The following is a list of the names of the persons who have been appointed to the various positions in the Department of the Interior, under the authority of the President of the United States.

The following is a list of the names of the persons who have been appointed to the various positions in the Department of the Interior, under the authority of the President of the United States.

The following is a list of the names of the persons who have been appointed to the various positions in the Department of the Interior, under the authority of the President of the United States.