

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8712140438 DOC. DATE: 87/12/11 NOTARIZED: NO DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH. NAME AUTHOR AFFILIATION  
 WOODY, C. O. Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards outside containment limitorque wire rept.  
 Evaluation concludes that Limitorque operators would have  
 performed designed safety function had operators been called  
 upon to do so. W/o encls to evaluation.

DISTRIBUTION CODE: A048D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 19  
 TITLE: OR/Licensing Submittal: Equipment Qualification

NOTES:

|           | RECIPIENT<br>ID CODE/NAME | COPIES<br>LTTR ENCL | RECIPIENT<br>ID CODE/NAME | COPIES<br>LTTR ENCL |
|-----------|---------------------------|---------------------|---------------------------|---------------------|
|           | PD2-2 LA                  | 1 0                 | PD2-2 PD                  | 1 0                 |
|           | McDONALD, D               | 1 1                 |                           |                     |
| INTERNAL: | ARM/DAF/LFMB              | 1 0                 | GC                        | 1 1                 |
|           | NRR/DEST/ADE              | 1 0                 | NRR/DEST/MEB              | 1 1                 |
|           | NRR/DEST/SGB              | 1 1                 | OGC/HDS2                  | 1 1                 |
|           | <u>REG FILE</u> 01        | 1 1                 | RES/DE/EIB                | 1 1                 |
| EXTERNAL: | LPDR                      | 1 1                 | NRC PDR                   | 1 1                 |
|           | NSIC                      | 1 1                 |                           |                     |





DECEMBER 11 1987

L-87-499

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Limitorque Valve Wiring Qualifications  
Unresolved Item 86-39-06

Our letter dated August 29, 1986 discussed the discovery of some wiring in Limitorque motor operated valves outside the containment which were on the environmental qualification list that may not have been fully supported by available documentation. In that letter we stated we would submit the results of our analysis of the as-found condition.

The attached evaluation concludes that the Limitorque operators would have performed their designed safety function had they been called upon to do so. Due to the size of the full report, the attachments to the evaluation have not been included but are available on site for your review.

Very truly yours,

C. O. Woody  
Executive Vice President

COW/SDF/cn:M:006  
Attachment

cc: Dr. J. Nelson Grace, Regional Administrator, Region II, USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant

8712140438 871211  
PDR ADDCK 05000250  
P PDR

A048  
11

