

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8909220142 DOC.DATE: 89/09/15 NOTARIZED: NO DOCKET #
 FACIL:50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH.NAME AUTHOR AFFILIATION
 WOODY,C.O.. Florida Power & Light Co. S66 Rpt
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards Inservice Insp Rept for 1987 unchanged outage.

DISTRIBUTION CODE: A047D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+526
 TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-2 LA	1 0	PD2-2 PD	2 2
EDISON,G	1 1		
INTERNAL: AEOD/DSP/TPAB	1 1	NRR/DEST/MEB 9H	1 1
NRR/DEST/MTB 9H	1 1	NUDOCS-ABSTRACT	1 1
OC/TFMB	1 0	OGC/HDS2	1 0
REG FILE 01	1 1	RES/DSIR/EIB	1 1
EXTERNAL: EG&G BROWN,B	1 1	EG&G ROCKHOLD,H	1 1
LPDR	1 1	NRC PDR	1 1
NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL 13

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S



FPL

P.O. Box 14000, Juno Beach, FL 33408-0420

SEPTEMBER 15 1989

L-89-328
10 CFR 50.55a

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Unit 4
Docket No. 50-251
Inservice Inspection Report

Attached are the following reports for Turkey Point Unit 4 in accordance with the provisions of the ASME Code, Section XI:

Form NIS-1 Owner's Data Report for Inservice Inspections, 1987 Unscheduled Outage

Form NIS-BB Owner's Data Report for Eddy Current Examination Results, Unit 4 Cycle 12 Refueling Outage

Form NIS-1 Owner's Data Report for Inservice Inspections, Unit 4 Cycle 12 Refueling Outage

Inservice Inspection Final Report Tables, Outage 1 (1988), Second Period, Second Interval for Class 1, 2, 3 and 4 Components

Form NIS-2 Owner's Report for Repairs or Replacements

Should there be any questions concerning this report, please contact us.

Very truly yours,

R. J. Acosta
C. O. Woody
Acting Senior Vice President - Nuclear

COW/PLP/gp

Attachments

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8909220142 890915
PDR ADOCK 05000251
Q PDC

an FPL Group company

A047
1/1

2025-01-01