

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9003010010 DOC.DATE: 90/02/20 NOTARIZED: NO DOCKET #  
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH.NAME AUTHOR AFFILIATION  
 HARRIS,K.N. Florida Power & Light Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept:on 900102-30,breached fire barriers & other  
 fire protection sys impairments.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	EDISON,G	1 1		
INTERNAL:	ACNW	2 2	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	NRR/DET/ECMB 9H	1 1
	NRR/DET/EMEB9H3	1 1	NRR/DET/ESGB 8D	1 1
	NRR/DLPQ/LHFB11	1 1	NRR/DLPQ/LPEB10	1 1
	NRR/DOEA/OEAB11	1 1	NRR/DREP/PRPB11	2 2
	NRR/DST/SELB 8D	1 1	NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
	<u>REG FILE 02</u>	1 1	RES/DSIR/EIB	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	EG&G WILLIAMS,S	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS,G	1 1	NSIC MURPHY,G.A	1 1
	NUDOCS FULL TXT	1 1		

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 35 ENCL 35

IA-2



FPL

P.O. Box 14000, Juno Beach, FL 33408-0420

FEB 20 1990

L-90-67

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555


Gentlemen:

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Special Report - Breached Fire Barriers and  
Other Fire Protection Systems Impairments

In accordance with Technical Specification 6.9.3.c, the  
attached Special Report is provided for your information.

Should There be any questions on this information please  
contact us.

Very truly yours,



K. N. Harris  
Vice President  
Turkey Point Plant Nuclear

KNH/DRP/DWH/dps

Attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II,  
USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant

9003010010 900220  
PDR ADOCK 05000250  
S PDC

TE22  
A006  
11

SPECIAL REPORT

**FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION**

PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC.

EVENT:

See attached list for Fire Protection Impairments (FPI) being reported.

CAUSE AND CORRECTIVE ACTIONS:

FPIs 3082, 3089, and 3130 were issued for the installation of conduits. FPI 3137 was issued for routine maintenance (O-SME-016.10) on the diesel fire pump. FPI 3117 was issued for access to areas where maintenance work was being performed. The plant continues to implement the compensatory measures as applicable.

STATUS UPDATE:

See attached list for Fire Protection Impairments that were previously reported and are now closed.

SPECIAL REPORT

**FIRE PROTECTION SYSTEM IMPAIRMENTS OPENED SINCE LAST REPORT  
WHICH HAVE BEEN OPEN LONGER THAN TECH. SPEC. LIMITS**

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>OPENED</u>	<u>CLOSED</u>
3082	Barrier 028N	01/02/90	01/22/90
3089	Barrier 025E	01/04/90	01/25/90
3117	Penetration 054F-H001	01/19/90	01/30/90
3130	Barrier 028W	01/25/90	
3137	Pump P-101, Diesel Fire	01/29/90	

**FIRE PROTECTION SYSTEM IMPAIRMENTS PREVIOUSLY  
NOT REPORTED CLOSED**

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>CLOSED</u>	<u>FPL LETTER &amp; DATE</u>
2383	Door 67-3	01/19/90	L-89-154 04/21/89
2390	Door 72-1	01/23/90	L-89-154 04/21/89
2398	Door 72-2	01/19/90	L-89-154 04/21/89
2402	Door 132-1	01/19/90	L-89-154 04/21/89
2403	Door 97-1	01/30/90	L-89-154 04/21/89
2418	Door 21-1	01/19/90	L-89-154 04/21/89
2420	Door 20-1	01/19/90	L-89-154 04/21/89
2423	Door 108A-2	01/19/90	L-89-154 04/21/89
2432	Door 95-1	01/07/90	L-89-154 04/21/90
2445	Door 62-1	01/19/90	L-89-154 04/21/90
2879	Door 108A-1	01/09/90	L-89-375 10/30/89
2985	Door 12-1	01/11/90	L-89-459 12/19/89
3012	Barrier 106F Penetration	01/10/90	L-90-17 01/12/90
3049	Barrier 047F Plug	01/19/90	L-90-17 01/12/90

