

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9003280259 DOC. DATE: 90/03/20 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 HARRIS, K.N. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 900131, breached fire barriers & other fire protection sys impairments.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-2 LA		1	1		PD2-2 PD		1	1
	EDISON, G		1	1					
INTERNAL:	ACNW		2	2		AEOD/DOA		1	1
	AEOD/DSP/TPAB		1	1		AEOD/ROAB/DSP		2	2
	DEDRO		1	1		NRR/DET/ECMB 9H		1	1
	NRR/DET/EMEB9H3		1	1		NRR/DET/ESGB 8D		1	1
	NRR/DLPQ/LHFB11		1	1		NRR/DLPQ/LPEB10		1	1
	NRR/DOEA/OEAB11		1	1		NRR/DREP/PRPB11		2	2
	NRR/DST/SELB 8D		1	1		NRR/DST/SICB 7E		1	1
	NRR/DST/SPLB8D1		1	1		NRR/DST/SRXB 8E		1	1
	REG FILE 02		1	1		RES/DSIR/EIB		1	1
	RGN2 FILE 01		1	1					
EXTERNAL:	EG&G STUART, V.A		1	1		L ST LOBBY WARD		1	1
	LPDR		1	1		NRC PDR		1	1
	NSIC MAYS, G		1	1		NSIC MURPHY, G.A		1	1
	NUDOCS FULL TXT		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 32 ENCL 32

Handwritten signature/initials



MAR 20 1990

L-90-100

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket No. 50-250 and 50-251
Special Report - Breached Fire Barriers
and Other Fire Protection Systems Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information please contact us.

Very truly yours,

K. N. Harris
Vice President
Turkey Point Plant Nuclear

KNH/DRP/rat

attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

9003280257 900320
FDR ADOCK 05000250
S PIR:

1/1
IF22
A001

SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC.

EVENT:

See attached list for Fire Protection Impairments (FPI) being reported.

CAUSE AND CORRECTIVE ACTIONS:

FPI 3168 was issued for the repair of thermolag. FPI 3183 is for the repair of a hole in barrier 068N. FPI 3186 was issued from a structural steel fireproofing surveillance, FPI 3199 was issued for repair of alarm point 35 trouble alarm. FPI's 3172, 3173 and 3235 were issued for access to areas for maintenance work. The remaining FPI's were issued for the installation of cables or conduits. The plant continues to implement the compensatory measures as applicable.

STATUS UPDATE:

See attached list for Fire Protection Impairments that were previously reported and are now closed.

SPECIAL REPORT

**FIRE PROTECTION SYSTEM IMPAIRMENTS OPENED SINCE LAST REPORT
WHICH HAVE BEEN OPEN FOR LONGER THAN TECH SPEC LIMITS**

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>OPENED</u>	<u>CLOSED</u>
3144	Barrier 041E	1/31/90	2/07/90
3163	Penetration 098N-E001	2/09/90	2/19/90
3164	Penetration 106F-E115	2/09/90	2/21/90
3168	Barrier Thermolag 4A1345	2/10/90	2/21/90
3172	Penetration 054F-H001	2/12/90	2/27/90
3173	Door 12-1	2/12/90	2/27/90
3178	Barrier 071N	2/13/90	
3183	Barrier 068N	2/14/90	
3186	Structural Steel 020	2/15/90	
3187	Barrier 070N	2/16/90	2/24/90
3191	Barrier 071N	2/20/90	
3199	Detector Alarm Pt 35	2/23/90	3/09/90
3221	Barrier 019E	2/28/90	
3222	Barrier 020N	2/28/90	
3233	Barrier 019E	3/02/90	
3234	Barrier 020N	3/02/90	
3235	Door 58-3	3/03/90	

**FIRE PROTECTION SYSTEM IMPAIRMENTS PREVIOUSLY
NOT REPORTED CLOSED**

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>CLOSED</u>	<u>FPL LETTER & DATE</u>
1584	Penetration 096F-E001	3/01/90	L-88-288 07/07/88
2409	Door 30-1	2/10/90	L-89-154 04/21/89
2413	Door 40-1	2/10/90	L-89-154 04/21/89
2414	Door 55-1	2/08/90	L-89-154 04/21/89
2416	Door 28-1	2/08/90	L-89-154 04/21/89
2436	Door 15-1	3/10/90	L-89-154 04/21/89
2628	Penetration 040F-M048	3/07/90	L-89-301 08/16/89
2807	Penetration 098S-M001	2/13/90	L-89-375 10/30/89
2808	Penetration 098N-M001	2/13/90	L-89-375 10/30/89
2851	Penetration Seals 106F-E	3/09/90	L-89-375 10/30/89
2911	Barrier 010E8	2/07/90	L-89-404 11/16/89
3130	Barrier 028W	2/08/90	L-90-67 02/20/90
3137	Pump P-101, Diesel Fire	2/08/90	L-90-67 02/20/90