

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9005230166 DOC.DATE: 90/05/18 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH.NAME AUTHOR AFFILIATION
 HARRIS,K.N. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept:fire barriers & other fire protection sys
 inoperable for greater than 7 days.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	EDISON,G	1 1		
INTERNAL:	ACNW	2 2	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	NRR/DET/ECMB 9H	1 1
	NRR/DET/EMEB9H3	1 1	NRR/DLPQ/LHFB11	1 1
	NRR/DLPQ/LPEB10	1 1	NRR/DOEA/OEAB11	1 1
	NRR/DREP/PRPB11	2 2	NRR/DST/SELB 8D	1 1
	NRR/DST/SICB 7E	1 1	NRR/DST/SPLB8D1	1 1
	NRR/DST/SRXB 8E	1 1	REG FILE 02	1 1
	RES/DSIR/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	EG&G STUART,V.A	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS,G	1 1	NSIC MURPHY,G.A	1 1
	NUDOCS FULL TXT	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 34 ENCL 34

FA-2
 WW



MAY 18 1990

L-90-185

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555


Gentlemen:

Re: Turkey Point Units 3 and 4
Docket No. 50-250 and 50-251
Special Report - Breached Fire Barriers
and Other Fire Protection Systems Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information please contact us.

Very truly yours,


K. N. Harris
Vice President
Turkey Point Plant Nuclear

KNH/DRP/TB/RAT/rat

attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

9005230166 900518
FDR ADOCK 05000250
S PNC

TE22
11

SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC. Please refer to the attached list of Fire Protection Impairments (FPI) being reported.

CAUSE AND CORRECTIVE ACTIONS:

FPI 3366 was issued for the removal and repair of fireproofing impaired for the installation of a support. FPI 3354 is for an impaired fire detector. FPI's 3311, 3312, 3352, 3353, and 3362 were issued for the installation of conduits. FPI 3314 was issued for the support of planned maintenance work. The plant continues to implement the compensatory measures as applicable.

STATUS UPDATE:

Please refer to the attached list of Fire Protection Impairments that were previously reported and are now closed.

SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS OPENED SINCE LAST REPORT WHICH HAVE BEEN OPEN FOR LONGER THAN SEVEN DAYS.

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>OPENED</u>	<u>CLOSED</u>
3311	Barrier 070E	04/03/90	04/13/90
3312	Barrier 070N	04/03/90	04/13/90
3314	Door 19-1	04/03/90	04/13/90
3352	Barrier 045E	04/24/90	05/03/90
3353	Barrier 047W	04/24/90	
3354	Detector Alarm Pt. 43	04/25/90	
3362	Barrier 021S	04/30/90	
3366	Structural Steel 058C	05/02/90	

FIRE PROTECTION SYSTEM IMPAIRMENTS PREVIOUSLY NOT REPORTED CLOSED

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>CLOSED</u>	<u>FPL LETTER & DATE</u>	
2429	Door 96-2	04/30/90	L-89-154	04/21/89
2446	Door 12-1	04/30/90	L-89-154	04/21/89
2748	Barrier 038F	05/04/90	L-90-364	10/13/89
2986	Penetration 040F-M009	04/30/90	L-89-459	12/19/89
3186	Structural Steel 020	04/16/90	L-90-100	03/20/90
3301	Door 30-1	04/21/90	L-90-139	04/17/90
3302	Door 72-2	04/19/90	L-90-139	04/17/90
3306	Structural Steel 104	04/09/90	L-90-139	04/17/90