

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9202030140 DOC. DATE: 92/01/27 NOTARIZED: NO DOCKET #
 FACIL: 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 PLUNKETT, T.F. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards five repts in accordance w/provisions of this requirement.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 200
 TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

NOTES: *See Reports*


	RECIPIENT ID. CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID. CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 0	PD2-2 PD	1 1
	AULUCK, R	2 2		
INTERNAL:	NRR/DET/ECMB 9H	1 1	NRR/DET/EMEB 7E	1 1
	NUDOCS-ABSTRACT	1 1	OC/LFMB	1 0
	OGC/HDS3	1 0	REG FILE 01	1 1
	RES/DSIR/EIB	1 1		
EXTERNAL:	EG&G BROWN, B	1 1	EG&G RANSOME, C	1 1
	NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 15 ENCL 12

MA
[Signature]





JAN 27 1992

L-92-012
10 CFR 50.55a

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Unit 4
Docket No. 50-251
Inservice Inspection Report

ASME Code, Section XI, (IWA-6230) requires that Inservice Inspection (ISI) Summary Reports be submitted within 90 days of completion of ISI conducted during a refueling outage. Please find attached the reports listed below, in accordance with the provisions of this requirement.

Form NIS-1 Owners' Data Report for Inservice Inspections.

Form NIS-BB Owners' Report for Eddy Current Examination Results.


Form NIS-2 Owners' Report for Repairs and Replacements.

Summary Report of Visual Examination and Functional Testing of Snubbers.

Summary of Inservice Inspection Examinations.

Should there be any questions concerning this report, please contact us.

Very truly yours,


T. F. Plunkett
Vice President
Turkey Point Nuclear

TFP/RJT/rt

Attachments

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

9202030140 920127
PDR ADOCK 05000251
P PDR

AD-47

Handwritten notes and scribbles in the top right corner.

147
