

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9210190125 DOC. DATE: 92/10/07 NOTARIZED: NO DOCKET #
FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
AUTH. NAME AUTHOR AFFILIATION
PLUNKETT, T.F. Florida Power & Light Co.
RECIP. NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Responds to generic ltr 90-06 re submission of proposed TS changes for Turkey Point, units 3 & 4 that started on 921001.

DISTRIBUTION CODE: A019D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
TITLE: Generic Ltr 90-06 Resolution of GE 70N94 PORVs & Block Valve Reliability

NOTES: NRR RAGHAVAN, L 05000250
NRR RAGHAVAN, L 05000251

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	AULUCK, R	1		
INTERNAL:	KIRKWOOD, R. NLS3	1 1	NRR/EMEB	1 1
	NRR/SRXB	1 1	PICKETT, D 13H15	1 1
	REG FILE 01	1 1	RES/DSIR/EIB	1 1
	RES/DSTR/RPSIB	1 1		
EXTERNAL:	NRC PDR	1 1	NUDOCS-ABSTRACT	1 1
NOTES:		1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.
ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 13 ENCL 13



OCT 07 1992

L-92-274

10 CFR 50.54 (f)

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Response to Generic Letter 90-06
Resolution of Generic Issues 70 and 94

Generic Letter (GL) 90-06, issued by the NRC on June 25, 1990, provided recommendations concerning resolution of Generic Issue (GI) 70 entitled "Power-Operated Relief Valve and Block Valve Reliability," and GI-94 entitled "Additional Low-Temperature Overpressure Protection for Light-Water Reactors."

Florida Power & Light Co. (FPL), by letter L-90-396, dated December 21, 1990, provided to the NRC the initial response to GL 90-06 for Turkey Point Units 3 and 4. The response specified that FPL would submit any necessary Technical Specification changes for Turkey Point Units 3 and 4 by the end of the Turkey Point Unit 3 Cycle 13 refueling outage, in accordance with the schedule specified in GL 90-06.

By NRC letter dated August 7, 1992 (L. Raghavan to J. Goldberg), the staff requested a final response to GL 90-06 by October 26, 1992. Per discussions with the NRC on September 22, 1992, FPL will submit the proposed Technical Specification changes for Turkey Point Units 3 and 4 by the end of the Turkey Point Unit 3 Cycle 13 refueling outage, which was started on October 1, 1992, and in accordance with our original commitment.


Should there be any questions please contact us.

Very truly yours,

T. F. Plunkett
Vice President
Turkey Point Nuclear

TFP/OIH

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
R. C. Butcher, Senior Resident Inspector, USNRC, Turkey
Point Plant



an FPL Group company

9019
40

10-10-68

10-10-68

10-10-68

10-10-68

10-10-68