

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9801080094 DOC.DATE: 97/12/30 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH.NAME AUTHOR AFFILIATION
 HOVEY,R.J. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 REYES, Region 2 (Post 820201)

SUBJECT: Provides notification of completion of actions identified in
 IFI 50-250/97-08 & 50-251/97-02,per GL 89-10 closure insp.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-3 PD	1 1	CROTEAU,R	1 1
INTERNAL: AEOD/SPD/RAB	1 1	AEOD/TTC	1 1
DEDRO	1 1	<u>FILE CENTER</u>	1 1
NRR/DRCH/HHFB	1 1	NRR/DRPM/PECB	1 1
NRR/DRPM/PERB	1 1	NUDOCS-ABSTRACT	1 1
OE DIR	1 1	OGC/HDS3	1 1
RGN2 FILE 01	1 1		
EXTERNAL: LITCO BRYCE,J H	1 1	NOAC	1 1
NRC PDR	1 1	NUDOCS FULLTEXT	1 1

NRR/DE
 RES/DBT
 RES/DST
 RES/DST/PBAB

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
 DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 21 ENCL 17

C
A
T
E
G
O
R
Y

1

D
O
C
U
M
E
N
T

5
1





DEC 30 1997

L-97-318

10 CFR 50.4

Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
Atlanta Federal Center
61 Forsyth St., SW, Suite 23T85
Atlanta, GA 30323

Dear Mr. Reyes:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Generic Letter 89-10 - Closure Inspection Follow-Up Items

The NRC Closure Inspection of Generic Letter (GL) 89-10, "Safety-Related Motor-Operated Valve Testing and Surveillance," for Turkey Point Units 3 and 4 was conducted during the period of July 14 through July 18, 1997. The results of the Closure Inspection are documented by NRC Integrated Inspection Report Nos. 50-250/97-08 and 50-251/97-08. The NRC inspectors concluded that the GL 89-10 implementation for Turkey Point Units 3 and 4 meets the intent of the GL in verifying the design-basis capabilities of its motor operated valves. However, the inspectors identified weaknesses in the documented justifications for assumptions applied in calculations, in evaluations of stem friction coefficients, and in extrapolations of dynamic test data. FPL committed to update the affected documentation, and to notify NRC Region II of the completion status by the end of the year. An Inspector Followup Item (IFI) 50-250, 251/97-08-02 was opened to track the completion of FPL's actions.

The purpose of this letter is to notify you that FPL's actions to update the affected documentation (addressed by IFI 50-250, 251/97-08-02) have been completed.

Please contact us if there are any questions about this submittal.

Very truly yours,

R. J. Hovey
Vice President
Turkey Point Plant

OIH

9801080094 971230
PDR ADOCK 05000250
P PDR

cc: Document Control Desk, USNRC, Washington, D.C.
Senior Resident Inspector, USNRC, Turkey Point Plant

000009

an FPL Group company



IEDI 10

ALL NRC/DE
RES/DET

R-IDS

