

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9803300352, DOC. DATE: 98/03/24 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 AUTH. NAME AUTHOR AFFILIATION
 HOVEY, R. J. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 97-009-01 re discovery that CR console switch
 for 3B SGFP was not in start position. LER is being revised
 to include attachment providing simplified auxiliary
 feedwater initiation logic diagram for loss of SGFPs.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 146
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

RECIPIENT ID CODE/NAME	COPIES	LTTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTTR	ENCL
PD2-3 PD	1		1	CROTEAU, R	1		1
INTERNAL: AEOD/SPD/RAB	2		2	AEOD/SPD/RRAB	1		1
FILE CENTER	1		1	NRR/DE/ECGB	1		1
NRR/DE/EELB	1		1	NRR/DE/EMEB	1		1
NRR/DRCH/HHFB	1		1	NRR/DRCH/HICB	1		1
NRR/DRCH/HOLB	1		1	NRR/DRCH/HQMB	1		1
NRR/DRPM/PECB	1		1	NRR/DSSA/SPLB	1		1
NRR/DSSA/SRXB	1		1	RES/DET/EIB	1		1
RGN2 FILE 01	1		1				
EXTERNAL: L ST LOBBY WARD	1		1	LITCO BRYCE, J H	1		1
NOAC POORE, W.	1		1	NOAC QUEENER, DS	1		1
NRC PDR	1		1	NUDOCS FULL TXT	1		1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24



MAR 24 1998

L-98-052
10 CFR 50.73

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Re: Turkey Point Unit 3
Docket No. 50-250
Reportable Event: 97-009-01
Date of Event: November 14, 1997
Console Switch Position Disabled Auxiliary Feedwater Auto Start Logic on 3B Steam
Generator Feedwater Pump Trip

The Licensee Event Report (LER) 250/97-009 is being revised to include the Attachment which provides the Simplified Auxiliary Feedwater Initiation Logic Diagram for the Loss of Steam Generator Feedwater Pumps.

Sincerely,

A handwritten signature in black ink, appearing to read 'R. J. Hovey', with a long horizontal flourish extending to the right.

R. J. Hovey
Vice President
Turkey Point Plant

SM

Attachment

cc: Regional Administrator, USNRC Region II
Senior Resident Inspector, USNRC, Turkey Point Plant

9803300352 980324
PDR ADDCK 05000250
S PDR

1/1
IE 22

