

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9807210011 DOC.DATE: 98/07/15 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 AUTH.NAME AUTHOR AFFILIATION
 HOVEY,R.J. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-003-00 re 980619 discovery that auxiliary feedwater sys was inoperable due to inadequate inservice testing of check valves.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+6
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-3 PD	1 1	JABBOUR, K	1 1
INTERNAL:	AEOD/SPD/RAB	2 2	AEOD/SPD/RRAB	1 1
	<u>FILE CENTER</u>	1 1	NRR/DE/ECGB	1 1
	NRR/DE/EELB	1 1	NRR/DE/EMEB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOHB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DET/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

C
A
T
E
G
O
R
Y

1

D
O
C
U
M
E
N
T



JUL 15 1998


L-98-184
10 CFR 50.73

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250, 50-251
Reportable Event: 98-003
Date of Event: June 19, 1998
Auxiliary Feedwater System Inoperable due to
Inadequate Inservice Testing of Check Valves

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR 50.73.

Very truly yours,



R. J. Hovey
Vice President
Turkey Point Plant

CLM
Attachment

cc: Regional Administrator, USNRC, Region II
Senior Resident Inspector, USNRC, Turkey Point Plant

9807210011 980715
PDR ADOCK 05000250
S PDR



2