

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9902050108 DOC. DATE: 99/01/29 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME: AUTH. AFFILIATION:
 HOVEY, R. J. Florida Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION:
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards rev 3 to "Turkey Point Nuclear Plant Recovery Plan." Rev does not decrease effectiveness of plan.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+54
 TITLE: OR Submittal: General Distribution

NOTES:

| | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL |
|-----------|---------------------------|---------------------|---------------------------|---------------------|
| | PD2-3 LA | 1 1 | PD2-3 PD | 1 1 |
| | JABBOUR, K | 1 1 | | |
| INTERNAL: | <u>FILE CENTER 01</u> | 1 1 | NRR/DE/ECGB/A | 1 1 |
| | NRR/DE/EMCB | 1 1 | NRR/DRCH/HICB | 1 1 |
| | NRR/DSSA/SPLB | 1 1 | NRR/DSSA/SRXB | 1 1 |
| | NRR/SPSB JUNG, I | 1 1 | NUDOCS-ABSTRACT | 1 1 |
| | OGC/HDS3 | 1 0 | | |
| EXTERNAL: | NOAC | 1 1 | NRC PDR | 1 1 |

MICROFILMED

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 13



JAN 29 1999

L-99-014

10 CFR 50.54(q)

10 CFR 50, Appendix E

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Recovery Plan - Revision 03

Florida Power and Light Company (FPL) has issued Revision 03 to the Turkey Point Recovery Plan. FPL has determined that the revision does not decrease the effectiveness of the Plan.

Attached is a summary of the changes to the Plan. Pursuant to 10 CFR 50.54 (q), enclosed is one copy of the revised Plan.

Should there be any questions, please contact us.

Very truly yours,

R. J. Hovey
Vice President
Turkey Point Plant

CLM

attachment
enclosure

cc: Regional Administrator, Region II, USNRC (2 copies)
Senior Resident Inspector, USNRC, Turkey Point Plant (no enclosure)

050004

9902050108 990129
PDR ADDCK 05000250
PDR

The following is a summary of the changes incorporated into Revision 03 of the Turkey Point Recovery Plan. The changes are organizational or administrative in nature, and do not represent a decrease in the effectiveness of the Recovery Plan or the Emergency Plan.

- Revised the Sample Recovery Organization figure to more correctly illustrate the structure of the recovery organization.
- Adjusted the recommended actions for the Emergency Control Officer and the Recovery Manager to more accurately reflect the actions of each as detailed in plant procedures.
- Added additional guidance for field radiological survey actions.
- Added additional guidance for coordinating ingress and egress of the plant with local authorities.
- Various editorial changes.

