



Brayton Point Energy, LLC
Brayton Point Power Station
1 Brayton Point Road
Somerset, MA 02725

08 December 2017

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Ladies & Gentlemen,

Dynegy-Brayton Point Energy LLC has removed all the Tritium Exit Signs from the property and sent them to SRB Technologies, Inc. (NC Radioactive Materials License # 034-0534-2) for proper disposal. The attached list contains all 96 Exit Signs including manufacturers, serial numbers, and installation addresses. Serial # C017166 Exit Sign was identified as defective and returned to the vender during 2009 construction.

Sincerely,

A handwritten signature in black ink that reads 'Thomas R. Moss'.

Thomas R. Moss,
Engineering & Maintenance Manager
O: 508 646 5267
C: 508 889-7806
thomas.r.moss@dynegy.com

Brayton Point Station: Self-Luminous Exit Signs												
Unit Number	Floor Elevation (ft)	Sign Elevation (ft)	Location Description	Distance from Column or Closest Adjacent Wall	Date of Installation	Date Manufactured	Date of Replacement	Serial Number	Tritium Content (curies)	Manufacturer	License No.	Model
3	50	59	REMOVED FROM ACTIVE USE	39' east of north west column	7/22/04	2/04	2/19	315018	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
1	15	25	REMOVED FROM ACTIVE USE	105' from south wall	8/2/04	2/04	2/19	315010	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
2	29	37	REMOVED FROM ACTIVE USE	15' from north wall	4/14/04	2/04	2/19	315011	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
1	15	25	REMOVED FROM ACTIVE USE	109' north from south boiler room wall	8/3/04	2/04	2/19	315012	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
4	15	25	REMOVED FROM ACTIVE USE	10' south from north west corner column	7/26/04	2/04	2/19	315013	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
4	15	24	REMOVED FROM ACTIVE USE	3' north from south west corner column	7/30/04	2/04	2/19	315014	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
4	15	25	REMOVED FROM ACTIVE USE	33' north from adjacent south wall	7/25/04	2/04	2/19	315015	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
3	50	59	REMOVED FROM ACTIVE USE	44' east from adjacent west wall, 2' south of door	7/22/04	2/04	2/19	315016	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
3	59	67	REMOVED FROM ACTIVE USE	7' east from south west corner column	7/16/04	2/04	2/19	315017	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
3	50	59	REMOVED FROM ACTIVE USE	15' west of north east corner column	7/22/04	2/04	2/19	315009	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
1	21	29	REMOVED FROM ACTIVE USE	3' south of north west corner column	7/13/04	2/04	2/19	314852	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
2	21	29	REMOVED FROM ACTIVE USE	4' south of north east corner column	7/14/04	2/04	2/19	314850	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
2	21	29	REMOVED FROM ACTIVE USE	3' south of north west corner column	7/14/04	2/04	2/19	314851	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
1	21	29	REMOVED FROM ACTIVE USE	3' south of north east column	7/13/04	2/04	2/19	314849	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
3	50	59	REMOVED FROM ACTIVE USE	25' east of column at north west corner	7/13/04	2/04	2/19	314853	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
1	15	24	REMOVED FROM ACTIVE USE	30' south of column "b3" north east corner of unit 1 boiler room	8/2/04	11/03	11/13	152,321	7.09	Forever-Lite, Inc.	None Provided	SLXTU1RB10
1	15	23	REMOVED FROM ACTIVE USE	45' from south boiler room wall	4/13/04	2/04	2/19	314855	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
1	29	37	REMOVED FROM ACTIVE USE	15' from north wall	4/14/04	2/04	2/19	314856	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
1	30' 5"	38	REMOVED FROM ACTIVE USE	13' 5" from south wall	6/28/04	2/04	2/19	314857	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E

Unit Number	Floor Elevation (ft)	Sign Elevation (ft)	Location Description	Distance from Column or Closest Adjacent Wall	Date of Installation	Date Manufactured	Date of Replacement	Serial Number	Tritium Content (curies)	Manufacturer	License No.	Model
2	32	40	REMOVED FROM ACTIVE USE	13' north from south/west corner column	7/12/04	2/04	2/19	314858	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
1	15	22.5	REMOVED FROM ACTIVE USE	39' from the west wall of room	9/2/04	2/04	2/19	314854	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	Betalux-E
C	16	24	REMOVED FROM ACTIVE USE	2' north from the south wall of the tunnel	1/31/05	6/04	6/19	C003988	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	16	24	REMOVED FROM ACTIVE USE	5' north from south wall of tunnel	1/28/05	6/04	6/19	C003989	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
1	16	24	REMOVED FROM ACTIVE USE	15' north from the south wall of the building	2/7/05	6/04	6/19	C003990	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
1	16	24	REMOVED FROM ACTIVE USE	14' east from the building's west wall	2/7/05	6/04	6/19	C003991	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
3	18	26	REMOVED FROM ACTIVE USE	15' north from the south wall of the building	2/7/05	6/04	6/19	C003992	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
3	18	26	REMOVED FROM ACTIVE USE	8' west from the east wall of the building	2/7/05	6/04	6/19	C003993	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	15	26	REMOVED FROM ACTIVE USE	8' north from the building's south wall	2/8/05	6/04	6/19	C003994	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	15	23	REMOVE FROM ACTIVE USE	10' east from the buildings west wall	2/8/05	6/04	6/19	C003995	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C SDA	32	39	REMOVE FROM ACTIVE USE	4'6" From North West Column, Measured Along The North Wall	7/27/12	6/04	6/19	C003996	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C SDA	50	57'2"	REMOVE FROM ACTIVE USE	7'5" From North West Column, Measured Along North Wall	7/27/17	6/04	6/19	C003997	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	11	15	REMOVED FROM ACTIVE USE	5' south from north wall of building	2/11/05	6/04	6/19	C003998	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	29	40	REMOVED FROM ACTIVE USE	9' north from the building's south wall	2/11/05	6/04	6/19	C003999	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	17	25	REMOVED FROM ACTIVE USE	7' west of column in north east corner of enclosure	2/14/05	6/04	6/19	C004000	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	20	28	REMOVED FROM ACTIVE USE	5' south from north wall of room	1/26/05	6/04	6/19	C003263	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	20	28	REMOVED FROM ACTIVE USE	4' south of north wall of room	1/26/05	6/04	6/19	C003264	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	15	23	REMOVED FROM ACTIVE USE	9.5' north from the south wall of the lunch room	1/20/05	11/03	11/13	152,322	7.09	Forever-Lite, Inc.	None Provided	SLXTU1RB10
1	50	58	REMOVED FROM ACTIVE USE	90' north from south boiler room wall	8/31/04	11/03	11/13	152,323	7.09	Forever-Lite, Inc.	None Provided	SLXTU1RB10
1	15	23	REMOVED FROM ACTIVE USE	120' from south boiler room wall	9/3/04	11/03	11/13	152,324	7.09	Forever-Lite, Inc.	None Provided	SLXTU1RB10

Unit Number	Floor Elevation (ft)	Sign Elevation (ft)	Location Description	Distance from Column or Closest Adjacent Wall	Date of Installation	Date Manufactured	Date of Replacement	Serial Number	Tritium Content (curies)	Manufacturer	License No.	Model
C	15	23	REMOVED FROM ACTIVE USE	3' north from south wall of hallway	1/20/05	11/03	11/13	152,325	7.09	Forever-Lite, Inc.	None Provided	SLXTU1RB10
1	37	44	REMOVED FROM ACTIVE USE	110' north from south boiler room wall	9/3/04	11/03	11/13	152,349	7.09	Forever-Lite, Inc.	None Provided	SLXTU1RB10
1	37	44	REMOVED FROM ACTIVE USE	110' north from south boiler room wall	9/3/04	11/03	11/13	152,350	7.09	Forever-Lite, Inc.	None Provided	SLXTU1RB10
C	15	23	REMOVED FROM ACTIVE USE	10' north of the south wall	1/21/05	11/03	11/13	152,351	7.09	Forever-Lite, Inc.	None Provided	SLXTU1RB10
C	15	23	REMOVED FROM ACTIVE USE	15' west from east wall of lab	1/21/05	11/03	11/13	152,352	7.09	Forever-Lite, Inc.	None Provided	SLXTU1RB10
C	15	23	REMOVED FROM ACTIVE USE	2' south from the north wall of the building	1/24/05	11/03	11/13	152,353	7.09	Forever-Lite, Inc.	None Provided	SLXTU1RB10
C	15	22	REMOVED FROM ACTIVE USE	7' south from the north wall of the building	1/25/05	11/03	11/13	152,354	7.09	Forever-Lite, Inc.	None Provided	SLXTU1RB10
X	X	X	REMOVED FROM ACTIVE USE	SECURED HOLDING @ GEN SERVICE ELECTRIC SHOP	SECURED 4/20/17	2/05	2/20	C01714 1	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
X	X	X	REMOVED FROM ACTIVE USE	SECURED HOLDING @ GEN SERVICE ELECTRIC SHOP	SECURED 4/20/17	2/05	2/20	C01714 2	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
X	X	X	REMOVED FROM ACTIVE USE	SECURED HOLDING @ GEN SERVICE ELECTRIC SHOP	SECURED 4/20/17	2/05	2/20	C01714 3	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
X	X	X	REMOVED FROM ACTIVE USE	SECURED HOLDING @ GEN SERVICE ELECTRIC SHOP	SECURED 4/20/17	2/05	2/20	C01714 4	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
X	X	X	REMOVED FROM ACTIVE USE	SECURED HOLDING @ GEN SERVICE ELECTRIC SHOP	SECURED 4/20/17	2/05	2/20	C01714 5	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C SDA2	32	39'10"	REMOVED FROM ACTIVE USE	34'4" From The South East Corner, Measured Along South Wall	3/1/11	2/05	2/20	C01714 6	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
1-2	25	33	REMOVED FROM ACTIVE USE	5' north of the south wall of the building	4/12/05	2/05	2/20	C01714 7	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
1-2	25	33	REMOVED FROM ACTIVE USE	5' north of the south wall	4/12/05	2/05	2/20	C01714 8	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	38	46	REMOVED FORM ACTIVE USE	FLYASH SILO #1	12/13/05	2/05	2/20	C01714 9	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	38	46	REMOVED FROM ACTIVE USE	FLYASH SILO #2	12/13/05	2/05	2/20	C01715 0	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	38	SE	REMOVED FROM ACTIVE USE	FLYASH SILO #3	12/13/05	2/05	2/20	C01715 1	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27103	034-0534-2	BX
C	38	46	REMOVED FROM SERVICE	FLYASH SILO #4	12/13/05	2/05	2/20	C01715 2	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-3	BX
							2/20					
C	15	23	REMOVED FROM ACTIVE USE	7.5 ft east of the western wall measured along the north wall	1/4/06	2/05	2/20	c017154	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX

Unit Number	Floor Elevation (ft)	Sign Elevation (ft)	Location Description	Distance from Column or Closest Adjacent Wall	Date of Installation	Date Manufactured	Date of Replacement	Serial Number	Tritium Content (curies)	Manufacturer	License No.	Model
C	15	23	REMOVED FROM ACTIVE USE	3 feet south of overhead door located in west wall of structure	1/4/06	2/05	2/20	c017153	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	15	26.5	REMOVED FROM ACTIVE USE	9 feet north along east wall measured from south/east corner of lobby	1/4/06	2/05	2/20	c017155	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	15	25	REMOVED FROM ACTIVE USE	6 feet north of entrance door to medical services room	1/4/06	2/05	2/20	c017156	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	15	23	REMOVED FROM ACTIVE USE	16' east of the west wall of the stock room measured along the south wall	1/6/06	2/05	2/20	c017158	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	15	23	REMOVED FROM ACTIVE USE	6' east of the overhead door in north wall of receiving	1/6/06	2/05	2/20	c017157	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	15	23	REMOVED FROM ACTIVE USE	10' west of the overhead door southern most overhead door on east wall of structure	1/13/06	2/05	2/20	c017159	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	15	23	REMOVED FROM ACTIVE USE	27' west of the overhead door southern most overhead door on east wall of structure	1/13/06	2/05	2/20	c017160	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	15	23	REMOVED FROM ACTIVE USE	44' from north west corner fo building	1/26/06	2/05	2/20	c017161	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	15	23	REMOVED FROM ACTIVE USE	5' from the north west corner of the structure measured along the north wall	1/26/06	2/05	2/20	c017162	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	15	23	REMOVED FROM ACTIVE USE	5' from the south east corner of the structure measured along the south wall	1/26/06	2/05	2/20	c017163	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	15	23	REMOVED FROM ACTIVE USE	44' nmeasured along the south wall from the south west corner of stair tower interior	8/21/06	2/05	2/20	c017164	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	37	45	REMOVED FROM ACTIVE USE	2' 4" from the north east corner, measured along the east wall	2/19/09	2/05	2/20	c017165	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	37	45	REMOVED FROM ACTIVE USE	11' from the east wall	2/25/09	2/05	2/20	C039066	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	37	45	Service Building; Chemistry lab section; Office Area; West wall above door to Unit; elevation 32' plant access	11' from the east wall	2/25/09	2/05	2/20	c017166	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	37	45	REMOVED FROM ACTIVE USE	17' 3" from NW corner of office area measured along the west wall	2/25/09	2/05	2/20	C039067	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	18	25	REMOVED FROM ACTIVE USE	15' 6" from the north wall of the room measured along east wall	3/5/09	1/06	1/21	c039068	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	20	27	REMOVED FROM ACTIVE USE	32" from west wall of safety office measured along north wall	2/23/09	1/06	1/21	c039069	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	18	25	REMOVED FROM ACTIVE USE	5' from the NW corner, measured along the west wall	3/5/09	1/06	1/21	c039070	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	29	36	REMOVED FROM ACTIVE USE	2' from the NW corner, measured along the north wall	3/5/09	1/06	1/21	c039071	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX

Unit Number	Floor Elevation (ft)	Sign Elevation (ft)	Location Description	Distance from Column or Closest Adjacent Wall	Date of Installation	Date Manufactured	Date of Replacement	Serial Number	Tritium Content (curies)	Manufacturer	License No.	Model
C	18	25	REMOVED FROM ACTIVE USE	3' from south outside wall, measured along the east wall	3/5/09	1/06	1/21	c039072	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	29	SE	REMOVED FROM ACTIVE USE	5' from the SE corner, measured along the south wall	2/18/09	1/06	1/21	c039073	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	29	37	REMOVED FROM ACTIVE USE	4' from the NE corner, measured along the east wall	2/18/09	1/06	1/21	c039074	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	18	25	REMOVED FROM ACTIVE USE	2' from the NE corner, measured along the east wall	3/5/09	1/06	1/21	c039075	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	50	59'2"	REMOVED FROM ACTIVE USE	2'5" From North / East-Corner, Measured South Along East Wall	4/16/10	1/06	1/21	c039226	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	50	58'5"	REMOVED FROM ACTIVE USE	16' From North / West Corner Measured East Along North Wall	4/16/10	1/06	1/21	c039227	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C SDA 1	200	207'6"	REMOVED FROM ACTIVE USE	5'8" From The North West Corner, Measured Along North Wall	3/26/10	1/06	1/21	c039228	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
1	32	39'8"	REMOVED FROM ACTIVE USE	2' From Column In South East Corner, Measured Along South Wall	3/1/11	1/06	1/21	c039229	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C SDA1	50	58'5"	REMOVED FROM ACTIVE USE	2'10" From The South East Corner, Measured Towards The North West Corner	1/7/11	1/06	1/21	c039231	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C SDA	32	39'6"	REMOVED FROM ACTIVE USE	11' From The South East Corner Of Building, Measured Along The South Wall	3/1/11	1/06	1/21	c039232	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C SDA1	47	54'10"	REMOVED FROM ACTIVE USE	39' From The South East Corner, Measured Along The South Wall	3/1/11	1/06	1/21	c039233	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	18	25'3"	REMOVED FROM ACTIVE USE	1'9" From West Wall Of Hallway, Measured Along North Wall	2/22/11	1/06	1/21	c039234	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	15	21'5"	REMOVED FROM ACTIVE USE	7'7" From The North East Corner, Measured Along North Wall	3/12/12	1/06	1/21	c039235	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	50	56'10"	REMOVED FROM ACTIVE USE	22" From East Wall, Measured Along North Wall	7/24/12	1/06	1/21	c039236	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	50	57	REMOVED FROM ACTIVE USE	22" From East Wall, Measured Along South Wall	7/24/12	1/06	1/21	c039237	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	37	44'7"	REMOVED FROM ACTIVE USE	2'2" From South Wall, Measured Along West Wall	7/25/12	1/06	1/21	c039238	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	37	44'5"	REMOVED FROM ACTIVE USE	5'9" From East Wall, Measured Along North Wall	7/25/12	1/06	1/21	c039239	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX
C	37	44'5"	REMOVED FROM ACTIVE USE	4'10" From East Wall, Measured Along South Wall	7/26/12	1/06	1/21	c039240	20	Safety Sign: SRB Technologies, Inc.; 2580 Landmark Dr.; Winston-Salem, NC 27104	034-0534-2	BX